





































41-41-15MHz-15MHz-16QAM-16QAM-41365-415
15-75RB#0-75RB#0-0.15~30MHz-PASS





41-41-15MHz-15MHz-16QAM-16QAM-41365-415
15-75RB#0-75RB#0-30~1000MHz-PASS





41-41-15MHz-15MHz-16QAM-16QAM-41365-415
15-75RB#0-75RB#0-1000~20000MHz-PASS



41-41-15MHz-15MHz-16QAM-16QAM-41365-415
15-75RB#0-75RB#0-20000~27000MHz-PASS









Date: 14-MAR-2025 05:02:06

41-41-15MHz-20MHz-QPSK-QPSK-39728-39899
-1RB#0-1RB#99-0.15~30MHz-PASS




Date: 14-MAR-2025 05:02:26

41-41-15MHz-20MHz-QPSK-QPSK-39728-39899-
1RB#0-1RB#99-30~1000MHz-PASS




Date: 14-MAR-2025 05:02:47

41-41-15MHz-20MHz-QPSK-QPSK-39728-39899
-1RB#0-1RB#99-1000~20000MHz-PASS




Date: 14-MAR-2025 05:03:07

41-41-15MHz-20MHz-QPSK-QPSK-39728-39899-
1RB#0-1RB#99-20000~27000MHz-PASS



Date: 16-MAR-2025 04:58:11



Date: 14-MAR-2025 04:58:30

