


APPENDIX 1: Photographs of test setup

Spurious Emission (Radiated) **(ANT.1)** **Front**




Rear



Spurious Emission (Radiated)
(ANT.2)
Front




Rear




Worst Case Position (Horizontal: X-axis/ Vertical:Y-axis)

(ANT.1)


X-axis



Y-axis



Z-axis



UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116

Facsimile : +81 596 24 8124

Worst Case Position (Horizontal: X-axis/ Vertical:Y-axis)

(ANT.2)

X-axis



Y-axis



Z-axis



UL Japan, Inc.

Head Office EMC Lab.

4383-326 Asama-cho, Ise-shi, Mie-ken 516-0021 JAPAN

Telephone : +81 596 24 8116

Facsimile : +81 596 24 8124