

SONOS

S45 Internal Photos




Photo 1: S45 with chassis open showing location of RF section and antenna locations.

Sonos Boston

2 Avenue de Lafayette
Boston, MA 02111
sonos.com

SONOS




Photo 2: “Left Side” Antennas. P/N: 105-00294 Front Haul (FH) 5&6 GHz
P/N: 105-00289 Back Haul (BH) 2.4, 5 & 6 GHz, P/N: 105-00291 BH 2.4, 5 & 6GHz

Sonos Boston

2 Avenue de Lafayette
Boston, MA 02111
sonos.com

SONOS




Photo 3: "Right Side" Antennas P/N: 105-00288 (BH) 2.4, 5 & 6 GHz, 105-00290 (BH) 2.4, 5 & 6 GHz, , P/N: 105-00292 (FH) 5&6 GHz, P/N: 105-00293 (FH) 5 & 6 GHz

Sonos Boston

2 Avenue de Lafayette
Boston, MA 02111
sonos.com

SONOS




Photo 4: S45 CPU/RF PCB with RF Shields




Photo 5: S45 CPU/RF PCB with RF Shields removed (RF Section highlighted).

Sonos Boston

2 Avenue de Lafayette
Boston, MA 02111
sonos.com

SONOS




Photo 6: Close up of RF Section top of PCB.

Sonos Boston

2 Avenue de Lafayette
Boston, MA 02111
sonos.com

SONOS




Photo 7: Close up of RF Section bottom of PCB.

-END-

Sonos Boston

2 Avenue de Lafayette
Boston, MA 02111
sonos.com