


TITLE: PLI Evaluation Report (RFI) FCC ID: SIU5406X
DRAWING: Q540601W.03.DWG.doc
BY: Laura Bramschreiber and Clyde Pineda

Page 23 of 40
Issued: 28 Sep 2004
Approved: Lee Pulver


FIGURE 5: PLI Photograph Number 5406C3334SJ-14 illustrates the top view of the EUT with the bottom cover removed showing the circuit side of the EUT printed circuit assembly, number PN-00057 Rev. 3. *[Short term confidentiality requested for this photo in FCC submission]*



TITLE: PLI Evaluation Report (RFI) FCC ID: SIU5406X
DRAWING: Q540601W.03.DWG.doc
BY: Laura Bramschreiber and Clyde Pineda

Page 24 of 40
Issued: 28 Sep 2004
Approved: Lee Pulver


FIGURE 6: PLI Photograph Number 5406C3334SJ-11 illustrates the component side of the EUT printed circuit assembly, number PN-00057 Rev. 3. *[Short term confidentiality requested for this photo in FCC submission]*



TITLE: PLI Evaluation Report (RFI) FCC ID: SIU5406X
DRAWING: Q540601W.03.DWG.doc
BY: Laura Bramschreiber and Clyde Pineda

Page 25 of 40
Issued: 28 Sep 2004
Approved: Lee Pulver

FIGURE 7: PLI Photograph Number 5406C3334SJ-12 illustrates a close up view of the added 0.001uF capacitor to C10. *[Short term confidentiality requested for this photo in FCC submission]*



Page 26 of 40
Issued: 28 Sep 2004
Approved: Lee Pulver