



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

November 1, 2004

RE: COP Security System Corp

FCC ID: SK2AUXTRX

I have a few comments on this Application. Depending on your responses, kindly understand there may be additional comments.

- 1.) Kindly refer to my comment letter of October 18, 2004. Please note that items 6.) and 7.) do not seem to be addressed. Please provide written details of the ASK modulation pulse train. In addition, we need some information on the timing sequence of the pulse train in addition to what has been presented in the Test Report. It is necessary for us to determine if this product was tested in a "worst case" manner which would maximize it's radiated field strength for comparison to the limits.

William H. Graff
President and Director of Engineering

[mailto: whgraff@AmericanTCB.com](mailto:whgraff@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.