



Elliott Laboratories Inc.
www.elliottlabs.com

684 West Maude Avenue
Sunnyvale, CA 94085-3518

408-245-7800 Phone
408-245-3499 Fax

American TCB

4/25/2005

In response to your comments please find our responses below:

1) The letter referenced in the last response for item 1 does not appear to have been provided.

A complete operational description for the 8-port, based on the 16-port description, has been uploaded.

2) Test report still antenna on page 7 of 113. Please correct.

Done, report uploaded as rev 4.

3) FYI...It appears that in response to previous item 13, that page 59 was not corrected, although pages 60 and 61 were corrected.

Page 59 has also been updated with the correct limit and included in the revised report.

4) Users manual should also indicate that this device should not be co-located with any other device.

The User Manual will be updated and uploaded to ATCB's website.

- R58645 rev 4.pdf (both applications)
- xs_userguide_c1 April 25.pdf.(both applications)
- Theory-of-Operation-XS3700.pdf (only for the 8-port version)

Regards,

A handwritten signature in blue ink that reads 'Mark Briggs'.

Mark Briggs
Principal Engineer