

US Tech
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Class II Permissive Change
SQB-NIVISMOD0001
09-0189
November 13, 2009
Nivis, LLC
2.4GHZ MOD2

3 Test Configuration Photographs



**Figure 1: Radiated Test Configuration Antenna 1
Omni Antenna 5.0dBi Gain (Front View)**

US Tech
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Class II Permissive Change
SQB-NIVISMOD0001
09-0189
November 13, 2009
Nivis, LLC
2.4GHZ MOD2



**Figure 2: Radiated Test Configuration Antenna 1
Omni Antenna 5.0dBi Gain (Rear View)**

US Tech
FCC ID:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Class II Permissive Change
SQB-NIVISMOD0001
09-0189
November 13, 2009
Nivis, LLC
2.4GHZ MOD2




Figure 3: Output Power Test Setup