


Appendix C – SAR Test Setup Photos



Test Position Front 0 mm Gap

Note: All cables are removed for testing.



Test Position Top 0 mm Gap

Note: All cables are removed for testing.



Test Position Right Side 0 mm Gap

Note: All cables are removed for testing.




Test Position Corner Side 0 mm Gap

Note: All cables are removed for testing.



Front of Device



Back of Device



Angle Picture of Left Side