



March 14, 2007

Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046

Attn: OET Dept.

Ref: Turbo Mode disablement for FCC Class II Permissive change for FCC ID:
STJ80411396001 - Letter of Attestation
Applicant: Hospira, Inc.

Dear Examiner,

This is to attest that the Turbo mode for the Custom DWL-AG132 Wireless USB Adapter has been disabled in the application software and is not available to the user.

Sincerely yours,


Mozammil Awan 03/14/07
Manager, Advanced Engineering