



802.11a\_5700MHz\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 7.MAR.2025 20:34:51

802.11a\_5720MHz\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 7.MAR.2025 20:36:30

802.11ac20\_5500MHz\_Chain 1




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 6.MAR.2025 22:15:38

802.11ac20\_5580MHz\_Chain 1




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 6.MAR.2025 22:17:35

802.11ac20\_5700MHz\_Chain 1




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 6.MAR.2025 22:19:39

802.11ac20\_5720MHz\_Chain 1




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 6.MAR.2025 22:26:10

802.11ac20\_5500MHz\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 7.MAR.2025 20:39:22

802.11ac20\_5580MHz\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 7.MAR.2025 20:41:14

802.11ac20\_5700MHz\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 7.MAR.2025 20:43:56

802.11ac20\_5720MHz\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 7.MAR.2025 20:46:11

802.11ac40\_5510MHz\_Chain 1




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 6.MAR.2025 22:28:17

802.11ac40\_5550MHz\_Chain 1



ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 6.MAR.2025 22:29:43


802.11ac40\_5670MHz\_Chain 1



ProjectNo.:2401T33438E-RF Tester:Brian LI

Date: 6.MAR.2025 22:33:25


802.11ac40\_5710MHz\_Chain 1



ProjectNo.:2401T33438E-RF Tester:Brian LI

Date: 6.MAR.2025 22:34:45


802.11ac40\_5510MHz\_Chain 2



ProjectNo.:2401T33438E-RF Tester:Brian LI

Date: 7.MAR.2025 20:48:16


802.11ac40\_5550MHz\_Chain 2



ProjectNo.:2401T33438E-RF Tester:Brian LI

Date: 7.MAR.2025 21:00:47


802.11ac40\_5670MHz\_Chain 2



ProjectNo.:2401T33438E-RF Tester:Brian LI

Date: 7.MAR.2025 21:02:02


802.11ac40\_5710MHz\_Chain 2



ProjectNo.:2401T33438E-RF Tester:Brian LI


Date: 7.MAR.2025 21:03:14

802.11ac80\_5530MHz\_Chain 1




ProjectNo.:2401T33438E-RF Tester:Brian Li  
Date: 6.MAR.2025 22:36:43

802.11ac80\_5610MHz\_Chain 1




ProjectNo.:2401T33438E-RF Tester:Brian Li  
Date: 6.MAR.2025 22:37:53

802.11ac80\_5690MHz\_Chain 1




ProjectNo.:2401T33438E-RF Tester:Brian Li  
Date: 6.MAR.2025 22:41:08

802.11ac80\_5530MHz\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian Li  
Date: 7.MAR.2025 21:04:47

802.11ac80\_5610MHz\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian Li  
Date: 7.MAR.2025 21:06:19

802.11ac80\_5690MHz\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian Li  
Date: 7.MAR.2025 21:08:44

802.11ax20\_5500MHz\_RU\_Full\_Chain 1




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 6.MAR.2025 22:46:50

802.11ax20\_5580MHz\_RU\_Full\_Chain 1




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 6.MAR.2025 22:49:11

802.11ax20\_5700MHz\_RU\_Full\_Chain 1




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 6.MAR.2025 22:51:20

802.11ax20\_5720MHz\_RU\_Full\_Chain 1




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 6.MAR.2025 22:53:36

802.11ax20\_5500MHz\_RU\_Full\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 7.MAR.2025 21:10:44

802.11ax20\_5580MHz\_RU\_Full\_Chain 2



ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 7.MAR.2025 21:14:00


802.11ax20\_5700MHz\_RU\_Full\_Chain 2



ProjectNo.:2401T33438E-RF Tester:Brian LI

Date: 7.MAR.2025 21:20:15


802.11ax20\_5720MHz\_RU\_Full\_Chain 2



ProjectNo.:2401T33438E-RF Tester:Brian LI

Date: 7.MAR.2025 21:36:11


802.11ax40\_5510MHz\_RU\_Full\_Chain 1



ProjectNo.:2401T33438E-RF Tester:Brian LI

Date: 6.MAR.2025 22:55:43


802.11ax40\_5550MHz\_RU\_Full\_Chain 1



ProjectNo.:2401T33438E-RF Tester:Brian LI

Date: 6.MAR.2025 22:56:57


802.11ax40\_5670MHz\_RU\_Full\_Chain 1



ProjectNo.:2401T33438E-RF Tester:Brian LI

Date: 6.MAR.2025 22:58:27


802.11ax40\_5710MHz\_RU\_Full\_Chain 1



ProjectNo.:2401T33438E-RF Tester:Brian LI


Date: 6.MAR.2025 22:59:40

802.11ax40\_5510MHz\_RU\_Full\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 7.MAR.2025 21:40:00

802.11ax40\_5550MHz\_RU\_Full\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 7.MAR.2025 21:41:34

802.11ax40\_5670MHz\_RU\_Full\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 7.MAR.2025 21:43:11

802.11ax40\_5710MHz\_RU\_Full\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 7.MAR.2025 21:44:19

802.11ax80\_5530MHz\_RU\_Full\_Chain 1




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 6.MAR.2025 23:01:16

802.11ax80\_5610MHz\_RU\_Full\_Chain 1




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 6.MAR.2025 23:02:46

802.11ax80\_5690MHz\_RU\_Full\_Chain 1




ProjectNo.:2401T33438E-RF Tester:Brian Li  
Date: 6.MAR.2025 23:04:37

802.11ax80\_5530MHz\_RU\_Full\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian Li  
Date: 7.MAR.2025 21:49:48

802.11ax80\_5610MHz\_RU\_Full\_Chain 2



ProjectNo.:2401T33438E-RF Tester:Brian Li  
Date: 7.MAR.2025 21:51:26


802.11ax80\_5690MHz\_RU\_Full\_Chain 2



ProjectNo.:2401T33438E-RF Tester:Brian Li  
Date: 7.MAR.2025 21:54:03


5725-5850MHz

802.11a\_5745MHz\_Chain 1



ProjectNo.:2401T33438E-RF Tester:Brian Li  
Date: 6.MAR.2025 23:07:58


802.11a\_5785MHz\_Chain 1



ProjectNo.:2401T33438E-RF Tester:Brian Li  
Date: 6.MAR.2025 23:09:59




802.11a\_5825MHz\_Chain 1



ProjectNo.:2401T33438E-RF Tester:Brian LI

Date: 6.MAR.2025 23:11:38


802.11a\_5745MHz\_Chain 2



ProjectNo.:2401T33438E-RF Tester:Brian LI

Date: 7.MAR.2025 21:56:42


802.11a\_5785MHz\_Chain 2



ProjectNo.:2401T33438E-RF Tester:Brian LI

Date: 7.MAR.2025 21:59:53


802.11a\_5825MHz\_Chain 2



ProjectNo.:2401T33438E-RF Tester:Brian LI

Date: 7.MAR.2025 22:01:38


802.11ac20\_5745MHz\_Chain 1



ProjectNo.:2401T33438E-RF Tester:Brian LI

Date: 6.MAR.2025 23:13:29


802.11ac20\_5785MHz\_Chain 1



ProjectNo.:2401T33438E-RF Tester:Brian LI


Date: 6.MAR.2025 23:15:27

802.11ac20\_5825MHz\_Chain 1




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 6.MAR.2025 23:17:10

802.11ac20\_5745MHz\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 7.MAR.2025 22:05:31

802.11ac20\_5785MHz\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 7.MAR.2025 22:07:14

802.11ac20\_5825MHz\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 7.MAR.2025 22:08:59

802.11ac40\_5755MHz\_Chain 1




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 6.MAR.2025 23:18:39

802.11ac40\_5795MHz\_Chain 1




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 6.MAR.2025 23:20:26

802.11ac40\_5755MHz\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 7.MAR.2025 22:10:31

802.11ac40\_5795MHz\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 7.MAR.2025 22:12:00

802.11ac80\_5775MHz\_Chain 1




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 6.MAR.2025 23:12:15

802.11ac80\_5775MHz\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 6.MAR.2025 23:14:25

802.11ax20\_5745MHz\_RU\_Full\_Chain 1




ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 6.MAR.2025 23:24:00

802.11ax20\_5785MHz\_RU\_Full\_Chain 1



ProjectNo.:2401T33438E-RF Tester:Brian LI  
Date: 6.MAR.2025 23:31:05


802.11ax20\_5825MHz\_RU\_Full\_Chain 1



ProjectNo.:2401T33438E-RF Tester:Brian LI

Date: 6.MAR.2025 23:33:34


802.11ax20\_5745MHz\_RU\_Full\_Chain 2



ProjectNo.:2401T33438E-RF Tester:Brian LI

Date: 7.MAR.2025 22:17:53


802.11ax20\_5785MHz\_RU\_Full\_Chain 2



ProjectNo.:2401T33438E-RF Tester:Brian LI

Date: 7.MAR.2025 22:21:02


802.11ax20\_5825MHz\_RU\_Full\_Chain 2



ProjectNo.:2401T33438E-RF Tester:Brian LI

Date: 7.MAR.2025 22:22:55


802.11ax40\_5755MHz\_RU\_Full\_Chain 1



ProjectNo.:2401T33438E-RF Tester:Brian LI

Date: 6.MAR.2025 23:35:10


802.11ax40\_5795MHz\_RU\_Full\_Chain 1



ProjectNo.:2401T33438E-RF Tester:Brian LI


Date: 6.MAR.2025 23:36:26

802.11ax40\_5755MHz\_RU\_Full\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian Li  
Date: 7.MAR.2025 22:24:52

802.11ax40\_5795MHz\_RU\_Full\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian Li  
Date: 7.MAR.2025 22:26:28

802.11ax80\_5775MHz\_RU\_Full\_Chain 1



ProjectNo.:2401T33438E-RF Tester:Brian Li  
Date: 6.MAR.2025 23:37:42

802.11ax80\_5775MHz\_RU\_Full\_Chain 2




ProjectNo.:2401T33438E-RF Tester:Brian Li  
Date: 7.MAR.2025 22:27:57


## For module YL7981

## 5150-5250MHz


802.11a\_5180MHz\_Chain 1




802.11a\_5200MHz\_Chain 1




802.11a\_5240MHz\_Chain 1




802.11a\_5180MHz\_Chain 2




802.11a\_5200MHz\_Chain 2




802.11a\_5240MHz\_Chain 2







ProjectNo.:2401T33438E-RF-1 Tester:Brian LI  
 Date: 6.MAR.2025 23:59:25




ProjectNo.:2401T33438E-RF-1 Tester:Brian LI  
 Date: 7.MAR.2025 00:01:24




ProjectNo.:2401T33438E-RF-1 Tester:Brian LI  
 Date: 7.MAR.2025 00:02:58



ProjectNo.:2401T33438E-RF-1 Tester:Brian LI  
 Date: 7.MAR.2025 23:48:06




ProjectNo.:2401T33438E-RF-1 Tester:Brian LI  
 Date: 7.MAR.2025 23:49:52




ProjectNo.:2401T33438E-RF-1 Tester:Brian LI  
 Date: 7.MAR.2025 23:51:44

802.11ac40\_5190MHz\_Chain 1




ProjectNo.:2401T33438E-RF-1 Tester:Brian Li  
Date: 7.MAR.2025 00:04:26

802.11ac40\_5230MHz\_Chain 1




ProjectNo.:2401T33438E-RF-1 Tester:Brian Li  
Date: 7.MAR.2025 00:05:36

802.11ac40\_5190MHz\_Chain 2




ProjectNo.:2401T33438E-RF-1 Tester:Brian Li  
Date: 7.MAR.2025 23:52:57

802.11ac40\_5230MHz\_Chain 2




ProjectNo.:2401T33438E-RF-1 Tester:Brian Li  
Date: 7.MAR.2025 23:53:54

802.11ac80\_5210MHz\_Chain 1



ProjectNo.:2401T33438E-RF-1 Tester:Brian Li  
Date: 7.MAR.2025 00:07:02


802.11ac80\_5210MHz\_Chain 2



ProjectNo.:2401T33438E-RF-1 Tester:Brian Li  
Date: 7.MAR.2025 23:55:04




802.11ax20\_5180MHz\_RU\_Full\_Chain 1




ProjectNo.:2401T33438E-RF-1 Tester:Brian Li  
Date: 7.MAR.2025 00:08:41

802.11ax20\_5200MHz\_RU\_Full\_Chain 1




ProjectNo.:2401T33438E-RF-1 Tester:Brian Li  
Date: 7.MAR.2025 00:11:50

802.11ax20\_5240MHz\_RU\_Full\_Chain 1




ProjectNo.:2401T33438E-RF-1 Tester:Brian Li  
Date: 7.MAR.2025 00:13:15

802.11ax20\_5180MHz\_RU\_Full\_Chain 2




ProjectNo.:2401T33438E-RF-1 Tester:Brian Li  
Date: 7.MAR.2025 23:57:06

802.11ax20\_5200MHz\_RU\_Full\_Chain 2



ProjectNo.:2401T33438E-RF-1 Tester:Brian Li  
Date: 8.MAR.2025 00:00:20

802.11ax20\_5240MHz\_RU\_Full\_Chain 2



ProjectNo.:2401T33438E-RF-1 Tester:Brian Li  
Date: 8.MAR.2025 00:01:50