



Appendix D. Internal Photographs

Inside View of The EUT




Report no. ETLE060428.194, Page 1 of 10



Component side view of Main board



Solder side view of Main board




Inside View of The LNB TUNER



Component side view of Power board




Solder side view of Power board




Appendix D. Internal Photographs

Component side view of Front Board





Solder side view of Front Board



Appendix D. Internal Photographs

Inside View of The EUT of RF Modulator



Appendix D. Internal Photographs

View of Bottom cover



View of Top cover



Appendix D. Internal Photographs

View of Front Cover

