



12/04/2009

Nemko Canada Inc  
303 River Road  
Ottawa, Ontario, Canada  
K1V 1H2

Attn: Director of Certification

FCC ID: T8H-SDC2K

**Class II Permissive Change Request**

Stanley Security Solutions, Inc. requests a Class II Permissive Change for the product listed with the FCC ID number above due to shielding modifications. We wish to remove the additional shielding "fence" and "cap" from the board, while leaving the PCB the same. We feel the PCB has adequate shielding designed into the layout and does not require the additional shielding mechanics currently in place. The radio frequency will not change from the previously certified device. The maximum output power will not change from the previously certified device. The radio frequency circuitry will not change from the previously certified device. Functional capabilities of the device will not change.

Sincerely,

A handwritten signature in black ink, appearing to read "Troy Brown".

Troy Brown  
Embedded / RF Systems Engineer  
Phone: (317) 806-3501  
Fax: (317) 806-3557  
Stanley Security Solutions, Inc  
6161 East 75th Street  
Indianapolis, IN 46250