



5605 Chemin St-François  
Ville St-Laurent, Québec  
H4S 1W6  
T: +1 (514) 745-8241  
F: +1 (514) 745-8630

Tuesday 19<sup>th</sup> of June 2012


Subject: FCC Change in identification of equipment statement.

To whom this may concern,

This letter serves to state the following information as per “2.933 Change in identification of equipment” guidance.

- (1) The original identification used on the equipment prior to the change in identification. : **T9RTAGX**
- (2) The date of the original grant of the equipment authorization. : **09/15/2011**
- (3) How the equipment bearing the modified identification differs from the original equipment. : ***The equipment does not differ in any way from the original equipment. Simply an identification number change.***
- (4) Whether the original test results continue to be representative of and applicable to the equipment bearing the changed identification. : ***The original test results continue to be representative of and applicable to the equipment bearing the changed identification. There are no changes in design, circuitry and construction.***
- (5) The photographs required by §2.1033(b) (7) or §2.1033(c) (12) showing the exterior appearance of the equipment, including the operating controls available to the user and the identification label. : ***See photos below.***

Regards,



Jason M Gallovich  
President (Tag)





IC: 6519A-TAGLR 4126254 Canada Inc. Model: TAG-LR  
FCC ID: T9RTAGLR LEOLUT ID#: 0421648H2F



TAG No. 000000000

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation. Protected under one or more US and Canadian patents. MADE IN CANADA  
Protégé sous un ou plusieurs brevets Canadiens et Américains.