



September 7, 2007

**FEDERAL COMMUNICATIONS COMMISSION**

7435 Oakland Mills Road  
Colombia, MD 21046  
U.S.A.

**Subject: Label Location**

**Applicant:** Applied RFID Solutions Inc.  
**Product:** WORKABOUT PRO G2  
**Model:** 7527SBTAVXB  
**FCC ID:** TBO7527SBTAVXB

Dear Sir/Madam,

The only flat surface available for the label on the exterior of the device is occupied by the safety label required by FDA for the scanner therefore the FCC label is located in the battery compartment. During shipping the battery and the battery cover are not installed on the device so that the FCC ID is easily visible. I hope this explanation is acceptable for locating the label in the battery compartment.

Yours truly,

A handwritten signature in black ink, appearing to read "Avihu Nachmani".

**Avihu (Avi) Nachmani**  
**President**  
**Applied RFID Solutions Inc.**  
**6272 East Boulevard, Suit 201.**  
**Vancouver, B.C., Canada, V6M 3V7**  
**Tel. 604-263-5529 Ex.5**  
**C. 604-721-5309**  
**www.Applied-RFID.com**  
**avihu@applied-rfid.com**