



September 25, 2007

FEDERAL COMMUNICATIONS COMMISSION

7435 Oakland Mills Road
Colombia, MD 21046
U.S.A.

Subject: Label Location

Applicant: Applied RFID Solutions Inc.
Product: WORKABOUT PRO G2
Model: 7527SBTAVXE
FCC ID: TBO7527SBTAVXE

Dear Sir/Madam,

The only flat surface available for the label on the exterior of the device is occupied by the safety label required by FDA for the scanner therefore the FCC label is located in the battery compartment. During shipping the battery and the battery cover are not installed on the device so that the FCC ID is easily visible. I hope this explanation is acceptable for locating the label in the battery compartment.

Regards,

A handwritten signature in black ink, appearing to read "Avihu Nachmani", followed by a small comma.

Avihu (Avi) Nachmani
President
Applied RFID Solutions Inc.
6272 East Boulevard, Suit 201.
Vancouver, B.C., Canada, V6M 3V7
Tel. 604-263-5529 Ex.5
C. 604-721-5309
www.Applied-RFID.com
avihu@applied-rfid.com