

3. General test set-up for radiated measurements.



Report No.:
23714RET


Date: 2006-04-10

FET18_00.DOC

Page: 4 of 6

Annex C

4. Test set-up for radiated measurements below 1 GHz.



Report No.:
23714RET

Date: 2006-04-10

FET18_00.DOC

Page: 5 of 6

Annex C

5. Test set-up for radiated measurements above 1 GHz.



Report No.:
23714RET

Date: 2006-04-10

FET18_00.DOC

Page: 6 of 6

Annex C