








Report No.: AAEMT/RF/250131-01-02






Report No.: AAEMT/RF/250131-01-02






Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02

Channel: 134





Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02


Channel: 134






Report No.: AAEMT/RF/250131-01-02

Channel: 134




Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02

Channel: 134



Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02

6dB BW 802.11ac40

Channel: 151



Channel: 159



Report No.: AAEMT/RF/250131-01-02

6dB BW 802.11ax40

Channel: 151



Channel: 159



Report No.: AAEMT/RF/250131-01-02

6dB BW 802.11be40



Channel: 151




Channel: 159





Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02

26dB BW 802.11ac80



Channel: 106



Channel: 122



Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02

26dB BW 802.11be80


Channel: 106




Channel: 122



Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02

26dB BW 802.11ax160

Channel: 114





26dB BW 802.11be160

Channel: 114




Report No.: AAEMT/RF/250131-01-02





Report No.: AAEMT/RF/250131-01-02

Channel: 48




Report No.: AAEMT/RF/250131-01-02





Report No.: AAEMT/RF/250131-01-02

Channel: 48




Report No.: AAEMT/RF/250131-01-02





Report No.: AAEMT/RF/250131-01-02

Channel: 48




Report No.: AAEMT/RF/250131-01-02





Report No.: AAEMT/RF/250131-01-02

Channel: 48




Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02


Channel: 48




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11a

Channel: 52




Channel: 60



Report No.: AAEMT/RF/250131-01-02


Channel: 64




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11n20

Channel: 52




Channel: 60



Report No.: AAEMT/RF/250131-01-02


Channel: 64




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11ac20

Channel: 52




Channel: 60



Report No.: AAEMT/RF/250131-01-02


Channel: 64




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11ax20


Channel: 52



Channel: 60




Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11be20

Channel: 52




Channel: 60



Report No.: AAEMT/RF/250131-01-02

Channel: 64




99% OBW 802.11a20

Channel: 100




Channel: 116




Report No.: AAEMT/RF/250131-01-02

Channel: 140




Report No.: AAEMT/RF/250131-01-02





Report No.: AAEMT/RF/250131-01-02

Channel: 140




Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02

Channel: 140




Report No.: AAEMT/RF/250131-01-02





Report No.: AAEMT/RF/250131-01-02

Channel: 140




Report No.: AAEMT/RF/250131-01-02





Report No.: AAEMT/RF/250131-01-02

Channel: 140




Report No.: AAEMT/RF/250131-01-02





Report No.: AAEMT/RF/250131-01-02

Channel: 165




Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02


Channel: 165




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11ac20

Channel: 149




Channel: 157





Report No.: AAEMT/RF/250131-01-02

Channel: 165




Report No.: AAEMT/RF/250131-01-02





Report No.: AAEMT/RF/250131-01-02

Channel: 165




Report No.: AAEMT/RF/250131-01-02





Report No.: AAEMT/RF/250131-01-02



Channel: 165



Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11ax40



Channel: 38



Channel: 46



Report No.: AAEMT/RF/250131-01-02




99% OBW 802.11n40

Channel: 54



Channel: 62




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11ac40

Channel: 54



Channel: 62




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11ax40

Channel: 54




Channel: 62




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11be40

Channel: 54




Channel: 62




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11n40


Channel: 102



Channel: 110




Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11ac40


Channel: 102



Channel: 110




Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11ax40


Channel: 102



Channel: 110




Report No.: AAEMT/RF/250131-01-02



99% OBW 802.11be40


Channel: 102



Channel: 110



Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11ax40

Channel: 151




Channel: 159




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11be40



Channel: 151





Channel: 159





Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11ac80

Channel: 106




Channel: 122




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11ax80

Channel: 106




Channel: 122




Report No.: AAEMT/RF/250131-01-02

99% OBW 802.11be80



Channel: 106




Channel: 122





Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02





Report No.: AAEMT/RF/250131-01-02





Report No.: AAEMT/RF/250131-01-02

MRU Antenna 1:



Report No.: AAEMT/RF/250131-01-02



Report No.: AAEMT/RF/250131-01-02

