









Report No.: AAEMT/RF/250131-01-03

802.11be80


Channel 135: 6625MHz





Date: 17.MAR.2025 23:40:07



Date: 20.MAR.2025 00:17:34









802.11ax20


Channel 189: 6895MHz




Date: 19.MAR.2025 19:33:29





Date: 19.MAR.2025 21:15:27







802.11ax40

Channel 195: 6925MHz



Report No.: AAEMT/RF/250131-01-03







Report No.: AAEMT/RF/250131-01-03

802.11ax80

Channel 199: 6945MHz




Date: 19.MAR.2025 18:18:48




Date: 19.MAR.2025 21:42:36

802.11ax160

Channel 207: 6985MHz





Date: 19.MAR.2025 18:18:48




Date: 19.MAR.2025 21:48:34


802.11be20

Channel 189: 6895MHz



Report No.: AAEMT/RF/250131-01-03







Report No.: AAEMT/RF/250131-01-03

802.11be40

Channel 195: 6925MHz




Date: 17.MAR.2025 23:25:21




Date: 19.MAR.2025 23:48:41


Report No.: AAEMT/RF/250131-01-03



Report No.: AAEMT/RF/250131-01-03





Report No.: AAEMT/RF/250131-01-03





802.11be160


Channel 207: 6985MHz



Antenna 1:









Report No.: AAEMT/RF/250131-01-03

802.11ax40

Channel 3: 5965MHz




Date: 19.MAR.2025 17:26:49




Date: 19.MAR.2025 21:02:40

Report No.: AAEMT/RF/250131-01-03




Report No.: AAEMT/RF/250131-01-03




802.11ax80

Channel 7: 5985MHz





Date: 19.MAR.2025 17:49:02



Date: 19.MAR.2025 21:35:16


Report No.: AAEMT/RF/250131-01-03






802.11ax160


Channel 15: 6025MHz




Date: 19.MAR.2025 18:07:38




Date: 19.MAR.2025 22:18:23




Report No.: AAEMT/RF/250131-01-03




Report No.: AAEMT/RF/250131-01-03



Report No.: AAEMT/RF/250131-01-03







Report No.: AAEMT/RF/250131-01-03

802.11be40


Channel 3: 5965MHz




Date: 18.MAR.2025 22:45:03



Date: 20.MAR.2025 17:36:38





Report No.: AAEMT/RF/250131-01-03




Report No.: AAEMT/RF/250131-01-03


802.11be80

Channel 7: 5985MHz






Report No.: AAEMT/RF/250131-01-03




Report No.: AAEMT/RF/250131-01-03

802.11be160

Channel 15: 6025MHz




Date: 18.MAR.2025 00:22:07




Date: 20.MAR.2025 18:23:38

Report No.: AAEMT/RF/250131-01-03




Report No.: AAEMT/RF/250131-01-03




802.11be320

Channel 63: 6265MHz




Date: 18.MAR.2025 00:17:27




Date: 20.MAR.2025 18:28:50

802.11ax20

Channel 97: 6435MHz



Date: 19.MAR.2025 00:42:32



Date: 19.MAR.2025 23:11:24

