



7/26/2022

Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046

To whom it may concern:

Impinj, Inc., hereby requests a Permissive Change Class II of the radio equipment certification for the Impinj R705 Portal Gateway Reader certification number, FCC ID: TWYR705. This product differs from the originally approved product in the following manner:

- (a) Associated digital circuitry. – PCB board layout change to incorporate interchangeable processor daughter card.
- (b) Functional Capabilities. – No changes to the functional capabilities of this product.
- (c) Antenna Characteristics. – No changes to the antenna characteristics of this product.
- (d) Cosmetic differences – No changes to the cosmetic differences of this product.

I do attest that the Field strength and/or RF Output readings remained the same or are lower than the originally approved product and that they did not increase therefore qualifying this product for this application type.

Sincerely,

Michelle Branum, KKC Certification Services, LLC. For Bill Ashley

Bill Ashley
Hardware Engineering
Impinj, Inc.

WWW.IMPINJ.COM

400 Fairview Ave N, Ste 1200 \ Seattle, WA 98109 \ +1.206.517.5300