





EUT Mode

802.11ax HE20 52RU38


Plot on Channel 6175 MHz




Plot on Channel 6475 MHz



Plot on Channel 6695 MHz



Plot on Channel 6995 MHz







EUT Mode

802.11ax HE20 52RU40


Plot on Channel 6415 MHz




Plot on Channel 6515 MHz



Plot on Channel 6855 MHz




Plot on Channel 6875 MHz





Plot on Channel 7115 MHz







EUT Mode

802.11ax HE20 106RU53


Plot on Channel 5935 MHz




Plot on Channel 5955 MHz



Plot on Channel 6175 MHz




Plot on Channel 6435 MHz






Plot on Channel 6475 MHz




10:11:39 AM 06/10/2024

Plot on Channel 6535 MHz




06:20:58 PM 05/29/2024

Plot on Channel 6695 MHz



10:27:52 AM 06/10/2024

Plot on Channel 6995 MHz




10:44:50 AM 06/10/2024



EUT Mode


802.11ax HE20 106RU54

Plot on Channel 6415 MHz




05:07:58 PM 05/29/2024

Plot on Channel 6515 MHz




06:11:53 PM 05/29/2024

Plot on Channel 6855 MHz



06:33:32 PM 05/29/2024


Plot on Channel 6875 MHz



06:42:50 PM 05/29/2024




Plot on Channel 7115 MHz






EUT Mode : 802.11ax HE40 Full RU

Plot on Channel 5965 MHz




10:43:43 AM 05/30/2024

Plot on Channel 6165 MHz




11:02:21 AM 05/30/2024

Plot on Channel 6405 MHz



11:05:34 AM 05/30/2024


Plot on Channel 6445 MHz




11:08:50 AM 05/30/2024




Plot on Channel 6485 MHz




Plot on Channel 6525 MHz



Plot on Channel 6565 MHz




Plot on Channel 6725 MHz







Plot on Channel 6845 MHz




Plot on Channel 6885 MHz



Plot on Channel 7005 MHz




Plot on Channel 7085 MHz






EUT Mode : 802.11ax HE80 Full RU


Plot on Channel 5985 MHz




Plot on Channel 6145 MHz



Plot on Channel 6385 MHz




Plot on Channel 6465 MHz






Plot on Channel 6545 MHz




12:26:23 PM 05/30/2024

Plot on Channel 6625 MHz




12:29:04 PM 05/30/2024

Plot on Channel 6705 MHz



12:31:31 PM 05/30/2024


Plot on Channel 6785 MHz



12:33:52 PM 05/30/2024




Plot on Channel 6865 MHz




12:37:28 PM 05/30/2024

Plot on Channel 6945 MHz



12:41:38 PM 05/30/2024

Plot on Channel 7025 MHz




12:44:00 PM 05/30/2024




EUT Mode : 802.11ax HE160 Full RU

Plot on Channel 6025 MHz




12:49:53 PM 05/30/2024

Plot on Channel 6185 MHz




12:54:11 PM 05/30/2024

Plot on Channel 6345 MHz



12:56:38 PM 05/30/2024


Plot on Channel 6505 MHz




12:59:26 PM 05/30/2024




Plot on Channel 6665 MHz



Plot on Channel 6825 MHz



Plot on Channel 6985 MHz






MIMO <Ant. 8+9(9)>


EUT Mode : 802.11a

Plot on Channel 5935 MHz




01:52:49 PM 05/29/2024

Plot on Channel 5955 MHz




01:48:02 PM 05/29/2024

Plot on Channel 6175 MHz



01:54:42 PM 05/29/2024

Plot on Channel 6415 MHz



01:59:14 PM 05/29/2024