



Annex C of test report R70363FCC 2nd version
EUT: DETECTOR III
Manufacturer: FAG Industrial Services GmbH




70363eut9.jpg: Main-PCB, top view

Annex C of test report R70363FCC 2nd version
EUT: DETECTOR III
Manufacturer: FAG Industrial Services GmbH




70363eut21.jpg: Main-PCB, bottom view

Annex C of test report R70363FCC 2nd version
EUT: DETECTOR III
Manufacturer: FAG Industrial Services GmbH




70363eut24.jpg: sub board, top view

Annex C of test report R70363FCC 2nd version
EUT: DETECTOR III
Manufacturer: FAG Industrial Services GmbH




70363eut25.jpg: sub board, bottom view

Annex C of test report R70363FCC 2nd version
EUT: DETECTOR III
Manufacturer: FAG Industrial Services GmbH




70363eut8.jpg: RF-PCB, top view

Annex C of test report R70363FCC 2nd version
EUT: DETECTOR III
Manufacturer: FAG Industrial Services GmbH




70363eut27.jpg: RF-PCB, bottom view

Annex C of test report R70363FCC 2nd version
EUT: DETECTOR III
Manufacturer: FAG Industrial Services GmbH




70363eut28.jpg: RF-PCB, detail view

Annex C of test report R70363FCC 2nd version
EUT: DETECTOR III
Manufacturer: FAG Industrial Services GmbH




70363eut30.jpg: connection board, top view

Annex C of test report R70363FCC 2nd version
EUT: DETECTOR III
Manufacturer: FAG Industrial Services GmbH



70363eut31.jpg: connection board, bottom view

Annex C of test report R70363FCC 2nd version
EUT: DETECTOR III
Manufacturer: FAG Industrial Services GmbH



70363eut32.jpg: connection board, bottom view detail