



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

November 29, 2007

RE: REGAL SUNNY INDUSTRIAL LIMITED

FCC ID: U686027B6030B

I have a few comments on this application. Depending on your responses, kindly understand there may be additional comments.

1. Please provide the block diagram of the bluetooth module.
2. Internal photos: Those PCB circuits and components under the covers shown at page 2 are required to be pictured.
Please provide the photos of PCB circuits and components under the covers..

George Chen
Chief Technical Officer - Asia

<mailto:george@atcb.com>

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.