

FCC ID: UIPSQ928M141 Test Report S/N: 45461997, 1998, 1999

Project:

1675

EXHIBIT 12 - PHOTOS - EMC SETUP

Figure E12.1 – Setup, Conducted Measurements





FCC ID: UIPSQ928M141 Test Report S/N: 45461997, 1998, 1999

Project:

Figure E12.2 – Setup, Radiated Tx Measurements, 30-1000MHz





FCC ID: UIPSQ928M141 Test Report S/N: 45461997, 1998, 1999

Project:

Figure E12.3 – Setup, Radiated Tx Measurements, Using LapTop






FCC ID: UIPSQ928M141 Test Report S/N: 45461997, 1998, 1999

Project:

Figure E12.4 – Setup, Radiated Rx Measurements, 30-1000MHz, with Cabling





FCC ID: UIPSQ928M141 Test Report S/N: 45461997, 1998, 1999

Project:

Figure E12.5 – Setup, Radiated Rx Measurements, 1-10GHz, with Cabling





FCC ID: UIPSQ928M141 Test Report S/N: 45461997, 1998, 1999

Project:

Figure E12.6 - Setup, Radiated Rx Measurements, 1-10GHz, with Cabling

