

Date: October 25, 2006

Reference: FCC ID UMYJLD-1

Thank you for your response to my previous questions. They resolved many of the issues. I do need the following, however, to complete the application.

- 1) It appears that the grantee code is no longer valid, please check with your client. I have also asked the FCC administrative section to see if they know what is wrong.

*Administrative issue has been resolved via EASADmin ... grantee code was changed from UMY to UDQ. Label, external photos showing label and report all updated with new grantee code.*

- 2) The plot showing the transmission duration is still too short to clearly demonstrate that the transmission is less than 5 seconds long. A plot of at least 5 seconds (preferably 10 – 20 seconds duration) with the transmission burst somewhere in the middle of the plot would help demonstrate that a single transmission is less than 5s long.

*Plot inserted into report*