



805 W. Franklin Street • Boise, ID • 83703

---

Date: 02.17.2011

## ATTESTATION LETTER

To whom it may concern:

The product, FCC ID: **UXX-PHS2000W**, is designed and limited in the firmware such that the built-in WiMAX cannot co-transmit at same time as an attached, external 3G dongle device. Only one modem/radio can be enabled at a time as described in page 11 of the user manual.

If you have any questions regarding the authorization, please don't hesitate to contact us. Thank you!

Sincerely,

A handwritten signature in blue ink that reads "Steven T. Wood".

---

**Steven T. Wood / Vice President of R&D**  
CradlePoint, Inc.  
TEL(208) 424-5054  
Facsimile(208) 429-6852  
Email: [swood@cradlepoint.com](mailto:swood@cradlepoint.com)