



April 13, 2012

**Regulatory Engineering**

Federal Communications Commission  
Office of Engineering and Technology  
Equipment Authorization Division  
7345 Oakland Mills Road  
Columbia MD 21046

Subject: Class II Permissive Change FCC ID: UZ7AP0622, Attestations and Requests

To the Commission:

Pursuant to CFR 2.1043, Motorola Solutions, Inc. hereby requests a Class II Permissive Change. The model name remains MODEL: AP-0622.

Modification:

Enable UNII Band 2 and Band 3 (5250~5350 MHz, 5470~5725 MHz) for this device. There are no changes in hardware or in existing RF relevant portion.

Motorola Solutions, Inc. hereby certifies that the submitted documents properly describe the device for which equipment certification is sought. We also certify that each unit manufactured, imported or marketed, as defined in FCC's regulations, will have affixed to it a label with the FCC ID as submitted for approval with this application.

In Addition, Motorola Solutions, Inc., also acknowledges that all responsibility for complying with the terms and conditions for Certification, still reside with Motorola Solutions, Inc., One Motorola Plaza, Holtsville, New York 11742 US.

In Addition, Motorola Solutions, Inc., as the grantee of this project FCC ID: UZ7AP0622, declare that the composite portion categorized as computer peripheral has been authorized under the Declaration of Conformity procedures supported by Sproton Test report No.: FD192220, FCC Test Firm Registration No.: 187376.

In Addition, Motorola Solutions, Inc., pursuant to Sections 0.457 and 0.459 of the Commission's Rules, the Applicant Hereby requests confidential treatment of information accompanying this Application for Listing as outlined below:

1. Operational Descriptions
2. Schematics
3. Block Diagrams
4. Parts List / Build of Materials



The above materials contain trade secrets and proprietary information not customarily released to the public. Public disclosure of these matters might be harmful to the Applicant and provide unjustified benefits to its competitors.

In Addition, Motorola Solutions, Inc., attest that this device does not support access, by any party End User or Professional Installer, to disable DFS. There are no controls or selections in the product firmware that can turn off/disable DFS.

In Addition, Motorola Solutions, Inc., will ensure that our MODEL: AP-0622 under FCC ID: UZ7AP0622 submitted by means of this application, will be continuously produced in compliance with FCC regulations. In relation to this, we accept all consequences of market surveillance performed by FCC or acting Certification Body as specified in the FCC's regulations.

If you have any questions regarding the authorization, please don't hesitate to contact me.

Respectfully,

A handwritten signature in blue ink that reads 'Mark S. Luksich'.

Mark S. Luksich  
DMTS, Regulatory  
631-738-5134  
[Mark.Luksich@motorolasolutions.com](mailto:Mark.Luksich@motorolasolutions.com)