FCC RF Test Report

APPLICANT : Zebra Technologies Corporation

EQUIPMENT: Mobile Computer

BRAND NAME : Zebra

MODEL NAME : MC330M

FCC ID : UZ7MC330M

STANDARD : FCC Part 15 Subpart C §15.247

CLASSIFICATION: (DSS) Spread Spectrum Transmitter

This is a variant report which is only valid together with the original test report. The product was received on Sep. 02, 2017 and testing was completed on Oct. 17, 2017. We, SPORTON INTERNATIONAL INC., would like to declare that the tested sample has been evaluated in accordance with the test procedures and has been in compliance with the applicable technical standards.

The test results in this report apply exclusively to the tested model / sample. Without written approval of SPORTON INTERNATIONAL INC., the test report shall not be reproduced except in full.

Reviewed by: Joseph Lin / Supervisor

Approved by: Jones Tsai / Manager



No. 52, Hwa Ya 1st Rd., Hwa Ya Technology Park, Kwei-Shan District, Tao Yuan City, Taiwan, R.O.C.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330M Page Number : 1 of 20
Report Issued Date : Nov. 08, 2017
Report Version : Rev. 02

1190

Report No.: FR790120-02A

TABLE OF CONTENTS

| RE۱ | VISION | N HISTORY | 3 |
|-----|---------------|---|-----|
| SUI | MMAR | Y OF TEST RESULT | 4 |
| 1 | GENE | RAL DESCRIPTION | 5 |
| | 1.1 | Applicant | 5 |
| | 1.2 | Manufacturer | 5 |
| | 1.3 | Product Feature of Equipment Under Test | 5 |
| | 1.4 | Product Specification of Equipment Under Test | 6 |
| | 1.5 | Modification of EUT | 6 |
| | 1.6 | Testing Location | 7 |
| | 1.7 | Applicable Standards | 7 |
| 2 | TEST | CONFIGURATION OF EQUIPMENT UNDER TEST | 8 |
| | 2.1 | Carrier Frequency Channel | 8 |
| | 2.2 | Test Mode | 9 |
| | 2.3 | Connection Diagram of Test System | .12 |
| | 2.4 | Support Unit used in test configuration and system | .12 |
| | 2.5 | EUT Operation Test Setup | .12 |
| 3 | TEST | RESULT | .13 |
| | 3.1 | Peak Output Power Measurement | .13 |
| | 3.2 | Radiated Band Edges and Spurious Emission Measurement | .14 |
| | 3.3 | Antenna Requirements | .18 |
| 4 | LIST | OF MEASURING EQUIPMENT | .19 |
| 5 | UNCE | RTAINTY OF EVALUATION | 20 |
| API | PENDI | X A. RADIATED SPURIOUS EMISSION | |
| API | PENDI | X B. RADIATED SPURIOUS EMISSION PLOTS | |
| API | PENDI | X C. DUTY CYCLE PLOTS | |
| API | PENDI | X D. SETUP PHOTOGRAPHS | |

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330M Page Number : 2 of 20
Report Issued Date : Nov. 08, 2017
Report Version : Rev. 02

Report No. : FR790120-02A

REVISION HISTORY

| REPORT NO. | VERSION | DESCRIPTION | ISSUED DATE |
|--------------|---------|---|---------------|
| FR790120-02A | Rev. 01 | Initial issue of report | Nov. 02, 2017 |
| FR790120-02A | Rev. 02 | Updating the description of Data Re-use in Summary of Test Result | Nov. 08, 2017 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330M Page Number : 3 of 20
Report Issued Date : Nov. 08, 2017
Report Version : Rev. 02

Report No. : FR790120-02A

SUMMARY OF TEST RESULT

| Report Section | FCC Rule | Description | Limit | Result | Remark |
|-------------------|-----------------------|--|-------------------------------|--------------|--|
| - | 15.247(a)(1) | Number of Channels | ≥ 15Chs | Not Required | - |
| - | 15.247(a)(1) | Hopping Channel Separation | ≥ 2/3 of 20dB BW | Not Required | - |
| - | 15.247(a)(1) | Dwell Time of Each Channel | ≤ 0.4sec in 31.6sec period | Not Required | - |
| - | 15.247(a)(1) | 20dB Bandwidth | NA | Not Required | - |
| - | - | 99% Bandwidth | - | Not Required | - |
| 3.1 | 15.247(b)(1) | Peak Output Power | ≤ 125 mW | Pass | - |
| - | 15.247(d) | Conducted Band Edges | ≤ 20dBc | Not Required | - |
| - | 15.247(d) | Conducted Spurious Emission | ≤ 20dBc | Not Required | - |
| 3.2 | 15.247(d) | Radiated Band Edges and Radiated Spurious Emission | 15.209(a) & 15.247(d) | Pass | Under limit 30.49 dB at 7323.000 MHz |
| - | 15.207 | AC Conducted Emission | 15.207(a) | Not Required | - |
| 3.3 | 15.203 & 15.247(b) | 3.3 Antenna Requirement | | Pass | - |

Note:

1. Not required means after assessing, test items are not necessary to carry out.

In this test report, performed conducted power measurement and BT/WLAN radiated spurious emission that based on the worst-case condition from the original model(FCC ID: UZ7MC330K) which can be referred to Sporton Report Number FR790120A.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330M Page Number : 4 of 20
Report Issued Date : Nov. 08, 2017
Report Version : Rev. 02

Report No.: FR790120-02A

^{2.} The original model (FCC ID: UZ7MC330K) and the variant model (FCC ID: UZ7MC330M) have identical PCB layout, antenna, SW implementation for Bluetooth/Wi-Fi. Based on their similarity, the test reports of FCC Part 15C & 15E (equipment class: DTS, DSS, NII) for the original model represent compliance for the variant model, and are referenced into the FCC filing of the variant model.

1 General Description

1.1 Applicant

Zebra Technologies Corporation

1 Zebra Plaza, Holtsville, NY 11742

1.2 Manufacturer

Zebra Technologies Corporation

1 Zebra Plaza, Holtsville, NY 11742

1.3 Product Feature of Equipment Under Test

| Product Feature | | | | | |
|---------------------------------|---|--|--|--|--|
| Equipment | Mobile Computer | | | | |
| Brand Name | Zebra | | | | |
| Model Name | MC330M | | | | |
| FCC ID | UZ7MC330M | | | | |
| | WLAN 11a/b/g/n HT20/HT40 | | | | |
| EUT supports Radios application | WLAN 11ac VHT20/VHT40/VHT80 | | | | |
| | Bluetooth BR/EDR/LE | | | | |
| HW Version | EV1b | | | | |
| SW Version | Android Version 7.1.2 | | | | |
| FW Version | W10: Aug 4 2017 12:57:11 version 7.35.205.8 (r) FWID | | | | |
| rw version | 01-895bc792 | | | | |
| Fusion Version | Fusion_BA_2.10.0.0.007_N-0809201717-N | | | | |
| MFD | 30AUG17 | | | | |
| EUT Stage | Engineering Sample | | | | |

<SKU List>

| | Standard | | | | | | | |
|-----|--------------|--------|------------|-----|---------|--|--|--|
| SKU | Type-scanner | camera | Audio Jack | NFC | Speaker | | | |
| 1 | GUN-SE4850 | Х | X | X | X | | | |
| 2 | GUN-SE4750 | Х | X | Х | X | | | |
| 3 | GUN-SE965 | Х | X | Х | X | | | |
| 4 | Brick-SE4850 | Х | X | Х | X | | | |
| 5 | Brick-SE4750 | Х | Х | Х | Х | | | |
| 6 | Brick-SE965 | Х | Х | Х | Х | | | |
| 7 | Rotate | Х | X | Х | Х | | | |

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330M Page Number : 5 of 20
Report Issued Date : Nov. 08, 2017
Report Version : Rev. 02

Report No.: FR790120-02A

| Specification of Accessories | | | | | | |
|--|-------------------|--------|--------------------|--------------------|--|--|
| Sentry 1X Battery | Brand Name | Zebra | Part Number | BT-000338-01 | | |
| Sentry 2X Battery | Brand Name | Zebra | Part Number | BT-000337-01 | | |
| MC32 1X Battery | Brand Name | Symbol | Part Number | 82-000011-01 | | |
| MC32 2X Battery | Brand Name | Symbol | Part Number | 82-000012-02 | | |
| Wall wart power supply(18W) | Brand Name | Zebra | Part Number | PWR-WUA5V12W0US | | |
| Charge Cable for Wall wart power supply | Brand Name | Zebra | Part Number | PWRS-14000-249R | | |
| HS2100 Earphone | Brand Name | Symbol | Part Number | HS2100-OTH | | |
| Quick Disconnect cable for HS2100 Headset | Brand Name | Symbol | Part Number | CBL-HS2100-QDC1-01 | | |
| RCH51 Earphone | Brand Name | Symbol | Part Number | RCH51 | | |
| Cable for RCH51 earphone | Brand Name | Symbol | Part Number | 25-124411-02R | | |
| U cable | Brand Name | Symbol | Part Number | CBL-MC33-USBCHG-01 | | |
| Gun Holster MC3000 | Brand Name | Symbol | Model Name | SG-MC3021212-01R | | |
| Holster MC30XX | Brand Name | Symbol | Model Name | 11-69293-01R | | |

1.4 Product Specification of Equipment Under Test

| Standards-related Product Specification | | | | |
|---|---|--|--|--|
| Tx/Rx Frequency Range | 2402 MHz ~ 2480 MHz | | | |
| Number of Channels | 79 | | | |
| Carrier Frequency of Each Channel | 2402+n*1 MHz; n=0~78 | | | |
| | Bluetooth BR(1Mbps) : 4.47 dBm (0.0028 W) | | | |
| Maximum Output Power to Antenna | Bluetooth EDR (2Mbps) : 4.25 dBm (0.0027 W) | | | |
| | Bluetooth EDR (3Mbps) : 4.32 dBm (0.0027 W) | | | |
| | Bluetooth BR (1Mbps) : GFSK | | | |
| Type of Modulation | Bluetooth EDR (2Mbps) : π /4-DQPSK | | | |
| | Bluetooth EDR (3Mbps) : 8-DPSK | | | |
| Antonno Typo / Goin | <ant. 1="">PIFA Antenna with gain 3.86 dBi</ant.> | | | |
| Antenna Type / Gain | <ant. 2="">PIFA Antenna with gain 3.63 dBi</ant.> | | | |

1.5 Modification of EUT

No modifications are made to the EUT during all test items.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330M Page Number : 6 of 20
Report Issued Date : Nov. 08, 2017
Report Version : Rev. 02

Report No.: FR790120-02A

1.6 Testing Location

Sporton Lab is accredited to ISO 17025 by Taiwan Accreditation Foundation (TAF code: 1190) and the FCC designation No. TW0007 under the FCC 2.948(e) by Mutual Recognition Agreement (MRA) in FCC Test.

| Test Site | SPORTON INTERNATIONAL INC. |
|--------------------|---|
| | No. 52, Hwa Ya 1 st Rd., Hwa Ya Technology Park, |
| Test Site Location | Kwei-Shan District, Tao Yuan City, Taiwan, R.O.C. |
| rest Site Location | TEL: +886-3-327-3456 |
| | FAX: +886-3-328-4978 |
| Test Site No. | Sporton Site No. |
| rest site No. | TH05-HY |

Note: The test site complies with ANSI C63.4 2014 requirement.

| Test Site SPORTON INTERNATIONAL INC. | | | |
|--------------------------------------|---|--|--|
| | No.58, Aly. 75, Ln. 564, Wenhua 3rd Rd. Guishan Dist, | | |
| Test Site Location | Taoyuan City, Taiwan (R.O.C.) | | |
| lest Site Location | TEL: +886-3-327-0868 | | |
| | FAX: +886-3-327-0855 | | |
| Test Site No. | Sporton Site No. | | |
| Test Site No. | 03CH12-HY | | |

Note: The test site complies with ANSI C63.4 2014 requirement.

1.7 Applicable Standards

According to the specifications of the manufacturer, the EUT must comply with the requirements of the following standards:

- FCC Part 15 Subpart C §15.247
- ANSI C63.10-2013

Remark:

- All test items were verified and recorded according to the standards and without any deviation during the test.
- 2. This EUT has also been tested and complied with the requirements of FCC Part 15, Subpart B, recorded in a separate test report.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330M Page Number : 7 of 20
Report Issued Date : Nov. 08, 2017
Report Version : Rev. 02

Report No.: FR790120-02A

2 Test Configuration of Equipment Under Test

2.1 Carrier Frequency Channel

| Frequency Band | Channel | Freq. (MHz) | Channel | Freq. (MHz) | Channel | Freq. (MHz) |
|-----------------|---------|----------------|---------|----------------|---------|----------------|
| | 0 | 2402 | 27 | 2429 | 54 | 2456 |
| | 1 | 2403 | 28 | 2430 | 55 | 2457 |
| | 2 | 2404 | 29 | 2431 | 56 | 2458 |
| | 3 | 2405 | 30 | 2432 | 57 | 2459 |
| | 4 | 2406 | 31 | 2433 | 58 | 2460 |
| | 5 | 2407 | 32 | 2434 | 59 | 2461 |
| | 6 | 2408 | 33 | 2435 | 60 | 2462 |
| | 7 | 2409 | 34 | 2436 | 61 | 2463 |
| | 8 | 2410 | 35 | 2437 | 62 | 2464 |
| | 9 | 2411 | 36 | 2438 | 63 | 2465 |
| | 10 | 2412 | 37 | 2439 | 64 | 2466 |
| | 11 | 2413 | 38 | 2440 | 65 | 2467 |
| | 12 | 2414 | 39 | 2441 | 66 | 2468 |
| 2400-2483.5 MHz | 13 | 2415 | 40 | 2442 | 67 | 2469 |
| | 14 | 2416 | 41 | 2443 | 68 | 2470 |
| | 15 | 2417 | 42 | 2444 | 69 | 2471 |
| | 16 | 2418 | 43 | 2445 | 70 | 2472 |
| | 17 | 2419 | 44 | 2446 | 71 | 2473 |
| | 18 | 2420 | 45 | 2447 | 72 | 2474 |
| | 19 | 2421 | 46 | 2448 | 73 | 2475 |
| | 20 | 2422 | 47 | 2449 | 74 | 2476 |
| | 21 | 2423 | 48 | 2450 | 75 | 2477 |
| | 22 | 2424 | 49 | 2451 | 76 | 2478 |
| | 23 | 2425 | 50 | 2452 | 77 | 2479 |
| | 24 | 2426 | 51 | 2453 | 78 | 2480 |
| | 25 | 2427 | 52 | 2454 | - | - |
| | 26 | 2428 | 53 | 2455 | - | - |

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330M Page Number : 8 of 20
Report Issued Date : Nov. 08, 2017
Report Version : Rev. 02

Report Template No.: BU5-FR15CBT Version 2.0

2.2 Test Mode

| | l Frequency | Blue | tooth Average Output Po | ower |
|---------|-------------|-----------------------|-------------------------|-----------------------|
| Channel | | | GFSK / 1Mbps | |
| | | | DH1 | DH3 |
| Ch00 | 2402MHz | 3.26 dBm | 3.25 dBm | 3.24 dBm |
| Ch39 | 2441MHz | <mark>3.46</mark> dBm | <mark>3.45</mark> dBm | <mark>3.41</mark> dBm |
| Ch78 | 2480MHz | 2.76 dBm | 2.75 dBm | 2.74 dBm |

| | Frequency | Blue | etooth Average Output Po | ower |
|---------|-----------|-----------------------|--------------------------|-----------------------|
| Channel | | | π/4-DQPSK / 2Mbps | |
| | | | 2DH1 | 2DH3 |
| Ch00 | 2402MHz | -0.53 dBm | -0.55 dBm | -0.57 dBm |
| Ch39 | 2441MHz | <mark>0.81</mark> dBm | <mark>0.80</mark> dBm | <mark>0.78</mark> dBm |
| Ch78 | 2480MHz | -0.01 dBm | -0.02 dBm | -0.05 dBm |

| | | Bluetooth Average Output Power | | | | | |
|---------|-----------|--------------------------------|-----------------------|-----------------------|--|--|--|
| Channel | Frequency | y 8-DPSK / 3Mbps | | | | | |
| | | 3DH1 | 3DH5 | | | | |
| Ch00 | 2402MHz | -0.51 dBm | -0.52 dBm | -0.55 dBm | | | |
| Ch39 | 2441MHz | <mark>0.87</mark> dBm | <mark>0.83</mark> dBm | <mark>0.81</mark> dBm | | | |
| Ch78 | 2480MHz | 0.00 dBm | -0.01 dBm | -0.03 dBm | | | |

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330M Page Number : 9 of 20
Report Issued Date : Nov. 08, 2017
Report Version : Rev. 02

Report No. : FR790120-02A

| | | Bluetooth Peak Output Power | | | | | |
|---------|-----------|-----------------------------|-----------------------|-----------------------|--|--|--|
| Channel | Frequency | cy GFSK / 1Mbps | | | | | |
| | | DH1 | DH3 | DH5 | | | |
| Ch00 | 2402MHz | 4.23 dBm | 4.19 dBm | 4.18 dBm | | | |
| Ch39 | 2441MHz | <mark>4.47</mark> dBm | <mark>4.45</mark> dBm | <mark>4.43</mark> dBm | | | |
| Ch78 | 2480MHz | 3.79 dBm | 3.78 dBm | 3.73 dBm | | | |

| | | Bluetooth Peak Output Power π/4-DQPSK / 2Mbps | | | | | |
|---------|-----------|---|-----------------------|-----------------------|--|--|--|
| Channel | Frequency | | | | | | |
| | | 2DH1 | 2DH3 | 2DH5 | | | |
| Ch00 | 2402MHz | 2.54 dBm | 2.50 dBm | 2.48 dBm | | | |
| Ch39 | 2441MHz | <mark>4.25</mark> dBm | <mark>4.08</mark> dBm | <mark>4.07</mark> dBm | | | |
| Ch78 | 2480MHz | 3.29 dBm | 3.09 dBm | 3.08 dBm | | | |

| | | Bluetooth Peak Output Power | | | | |
|----------------------------------|---------|-----------------------------|-----------------------|-----------------------|--|--|
| Channel Frequency 8-DPSK / 3Mbps | | | | | | |
| | | 3DH1 | 3DH5 | | | |
| Ch00 | 2402MHz | 2.73 dBm | 2.72 dBm | 2.70 dBm | | |
| Ch39 | 2441MHz | <mark>4.32</mark> dBm | <mark>4.16</mark> dBm | <mark>4.15</mark> dBm | | |
| Ch78 | 2480MHz | 3.28 dBm | 3.27 dBm | 3.25 dBm | | |

Remark: The data rate was set in 1Mbps for all the test items due to the highest RF output power.

- a. The EUT has been associated with peripherals and configuration operated in a manner tended to maximize its emission characteristics in a typical application. Frequency range investigated: conduction emission (150 kHz to 30 MHz), radiation emission (9 kHz to the 10th harmonic of the highest fundamental frequency or to 40 GHz, whichever is lower). For radiated measurement, pre-scanned in three orthogonal panels, X, Y, Z. The worst cases (Y plane) were recorded in this report, and the worst mode of radiated spurious emissions is Bluetooth 1Mbps mode.
- b. AC power line Conducted Emission was tested under maximum output power.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330M Page Number : 10 of 20
Report Issued Date : Nov. 08, 2017
Report Version : Rev. 02

Report No.: FR790120-02A

The following summary table is showing all test modes to demonstrate in compliance with the standard.

| Summary table of Test Cases | | | | | |
|-----------------------------|-------------------------|--|--|--|--|
| Radiated | Bluetooth BR 1Mbps GFSK | | | | |
| Test Cases | Mode 1: CH39_2441 MHz | | | | |

Remark:


- For radiated test cases, the worst mode data rate 1Mbps was reported only, because this data rate
 has the highest RF output power at preliminary tests, and the conducted spurious emissions and
 conducted band edge measurement for each data rate are no worse than 1Mbps, and no other
 significantly frequencies found in conducted spurious emission.
- 2. For radiated test cases, the test was performed with SKU 7, Keypad (46), MC32 1X Battery, USB Link with Adapter, PWR-WUA5V12W0US(LV6).

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330M Page Number : 11 of 20
Report Issued Date : Nov. 08, 2017
Report Version : Rev. 02

Report No.: FR790120-02A

2.3 Connection Diagram of Test System



2.4 Support Unit used in test configuration and system

| Item | Equipment | Trade Name | Model Name | FCC ID | Data Cable | Power Cord |
|------|---------------------------|------------|------------|--------|------------|--|
| 1. | Bluetooth Base Station | R&S | CBT32 | N/A | N/A | Unshielded, 1.8 m |
| 2. | Notebook-40(Tx) | Lenovo | E335 | N/A | N/A | AC I/P: Unshielded, 1.2 m DC O/P: Shielded, 1.8 m |
| 3. | Notebook-53(Rx) | ASUS | K42J | N/A | N/A | AC I/P: Unshielded, 1.2 m DC O/P: Shielded, 1.8 m |

2.5 EUT Operation Test Setup

For Bluetooth function, the RF utility, "command" was installed in notebook which was programmed in order to make the EUT get into the engineering modes to contact with Bluetooth base station for continuous transmitting and receiving signals.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330M Page Number : 12 of 20
Report Issued Date : Nov. 08, 2017
Report Version : Rev. 02

Report No.: FR790120-02A

3 Test Result

3.1 Peak Output Power Measurement

3.1.1 Limit of Peak Output Power

Section 15.247 (b) The maximum peak conducted output power of the intentional radiator shall not exceed the following: (1) For frequency hopping systems operating in the 2400-2483.5 MHz band employing at least 75 non-overlapping hopping channels, and all frequency hopping systems in the 5725-5850 MHz band: 1 watt. For all other frequency hopping systems in the 2400-2483.5 MHz band 0.125 watts. The power limit for 1Mbps, 2Mbps, 3Mbps and AFH modes are 0.125 watts.


3.1.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

3.1.3 Test Procedures

- 1. The testing follows ANSI C63.10-2013 clause 7.8.5.
- 1. The RF output of EUT was connected to the power meter by RF cable and attenuator. The path loss was compensated to the results for each measurement.
- 2. Set to the maximum power setting and enable the EUT transmit continuously.
- 3. Measure the conducted output power with cable loss and record the results in the test report.
- 4. Measure and record the results in the test report.

3.1.4 Test Setup



3.1.5 Test Result of Peak Output Power

Please refer to section 2.2 of the report.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330M Page Number : 13 of 20
Report Issued Date : Nov. 08, 2017
Report Version : Rev. 02

Report No.: FR790120-02A

3.2 Radiated Band Edges and Spurious Emission Measurement

3.2.1 Limit of Radiated Band Edges and Spurious Emission

In any 100 kHz bandwidth outside the intentional radiator frequency band, all harmonics/spurious must be at least 20 dB below the highest emission level within the authorized band. In addition, radiated emissions which fall in the restricted bands must also comply with the limits as below.

| Frequency | Field Strength | Measurement Distance |
|---------------|--------------------|----------------------|
| (MHz) | (microvolts/meter) | (meters) |
| 0.009 - 0.490 | 2400/F(kHz) | 300 |
| 0.490 - 1.705 | 24000/F(kHz) | 30 |
| 1.705 – 30.0 | 30 | 30 |
| 30 – 88 | 100 | 3 |
| 88 – 216 | 150 | 3 |
| 216 - 960 | 200 | 3 |
| Above 960 | 500 | 3 |

3.2.2 Measuring Instruments

The measuring equipment is listed in the section 4 of this test report.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330M Page Number : 14 of 20
Report Issued Date : Nov. 08, 2017
Report Version : Rev. 02

Report No.: FR790120-02A

3.2.3 Test Procedures

- 1. The EUT was placed on a turntable with 0.8 meter for frequency below 1GHz and 1.5 meter for frequency above 1GHz respectively above ground.
- 2. The EUT was set 3 meters from the interference receiving antenna, which was mounted on the top of a variable height antenna tower.
- 3. For each suspected emission, the EUT was arranged to its worst case and then tune the Antenna tower (from 1 m to 4 m) and turntable (from 0 degree to 360 degrees) to find the maximum reading. A pre-amp and a high pass filter are used for the test in order to get better signal level to comply with the guidelines.
- 4. Set to the maximum power setting and enable the EUT transmit continuously.
- 5. Use the following spectrum analyzer settings:
 - (1) Span shall wide enough to fully capture the emission being measured;
 - (2) Set RBW=100 kHz for f < 1 GHz, RBW=1MHz for f>1GHz; VBW ≥ RBW; Sweep = auto; Detector function = peak; Trace = max hold for peak
 - (3) For average measurement: use duty cycle correction factor method per 15.35(c).Duty cycle = On time/100 milliseconds

On time = $N_1*L_1+N_2*L_2+...+N_{n-1}*LN_{n-1}+N_n*L_n$

Where N_1 is number of type 1 pulses, L_1 is length of type 1 pulses, etc.

Average Emission Level = Peak Emission Level + 20*log(Duty cycle)

6. Corrected Reading: Antenna Factor + Cable Loss + Read Level - Preamp Factor = Level


Note: The average levels were calculated from the peak level corrected with duty cycle correction factor (-24.77dB) derived from 20log (dwell time/100ms). This correction is only for signals that hop with the fundamental signal, such as band-edge and harmonic. Other spurious signals that are independent of the hopping signal would not use this correction.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330M Page Number : 15 of 20
Report Issued Date : Nov. 08, 2017
Report Version : Rev. 02


Report No.: FR790120-02A

3.2.4 Test Setup

For radiated emissions below 30MHz



For radiated emissions from 30MHz to 1GHz




SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330M Page Number : 16 of 20
Report Issued Date : Nov. 08, 2017
Report Version : Rev. 02

Report No.: FR790120-02A

For radiated emissions above 1GHz



3.2.5 Test Results of Radiated Spurious Emissions (9 kHz ~ 30 MHz)

The low frequency, which started from 9 kHz to 30MHz, was pre-scanned and the result which was 20dB lower than the limit line per 15.31(o) was not reported.

3.2.6 Test Result of Radiated Spurious at Band Edges

Please refer to Appendix A and B.

3.2.7 Duty Cycle

Please refer to Appendix C.

3.2.8 Test Result of Radiated Spurious Emission (30MHz ~ 10th Harmonic)

Please refer to Appendix A and B.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330M Page Number : 17 of 20
Report Issued Date : Nov. 08, 2017
Report Version : Rev. 02

Report No.: FR790120-02A

3.3 Antenna Requirements

3.3.1 Standard Applicable

If directional gain of transmitting antennas is greater than 6dBi, the power shall be reduced by the same level in dB comparing to gain minus 6dBi. The use of a permanently attached antenna or of an antenna that uses a unique coupling to the intentional radiator shall be considered sufficient to comply with the rule.

3.3.2 Antenna Anti-Replacement Construction

An embedded-in antenna design is used.

3.3.3 Antenna Gain

The antenna peak gain of EUT is less than 6 dBi. Therefore, it is not necessary to reduce maximum peak output power limit.

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330M Page Number : 18 of 20
Report Issued Date : Nov. 08, 2017
Report Version : Rev. 02

Report No.: FR790120-02A

4 List of Measuring Equipment

| Instrument | Manufacturer | Model No. | Serial No. | Characteristics | Calibration Date | Test Date | Due Date | Remark |
|------------------------------|-----------------------|-------------------------------------|-----------------|------------------|---------------------|----------------------------------|---------------|--------------------------|
| Power Meter | Anritsu | ML2495A | 0932001 | N/A | Sep. 26, 2017 | Oct. 04, 2017 | Sep. 25, 2018 | Conducted (TH05-HY) |
| Power Sensor | Anritsu | MA2411B | 0846202 | 300MHz~40GH z | Sep. 26, 2017 | Oct. 04, 2017 | Sep. 25, 2018 | Conducted (TH05-HY) |
| Spectrum Analyzer | Rohde & Schwarz | FSP30 | 101067 | 9kHz ~ 30GHz | Nov. 17, 2016 | Oct. 04, 2017 | Nov. 16, 2017 | Conducted (TH05-HY) |
| BT Base Station (Measure) | Rohde & Schwarz | CBT | 101136 | BT 3.0 | Sep. 20, 2017 | Oct. 04, 2017 | Sep. 19, 2018 | Conducted (TH05-HY) |
| Amplifier | SONOMA | 310N | 187312 | 9kHz~1GHz | Nov. 10, 2016 | Oct. 13, 2017 ~ Oct. 17, 2017 | Nov. 09, 2017 | Radiation (03CH12-HY) |
| Bilog Antenna | TESEQ | CBL 6111D&00800 N1D01N-06 | 35413&02 | 30MHz~1GHz | Jan. 07, 2017 | Oct. 13, 2017 ~ Oct. 17, 2017 | Jan. 06, 2018 | Radiation (03CH12-HY) |
| EMI Test Receiver | Rohde & Schwarz | ESU26 | 100390 | 20Hz~26.5GHz | Dec. 23, 2016 | Oct. 13, 2017 ~ Oct. 17, 2017 | Dec. 22, 2017 | Radiation (03CH12-HY) |
| Horn Antenna | SCHWARZBE CK | BBHA 9120D | 9120D-132 8 | 1GHz ~ 18GHz | Oct. 25, 2016 | Oct. 13, 2017 ~ Oct. 17, 2017 | Oct. 24, 2017 | Radiation (03CH12-HY) |
| Preamplifier | MITEQ | AMF-7D-0010 1800-30-10P | 1815698 | 1GHz~18GHz | Dec. 01, 2016 | Oct. 13, 2017 ~ Oct. 17, 2017 | Nov. 30, 2017 | Radiation (03CH12-HY) |
| Preamplifier | Keysight | 83017A | MY532701 48 | 1GHz~26.5GHz | Jan. 12, 2017 | Oct. 13, 2017 ~ Oct. 17, 2017 | Jan. 11, 2018 | Radiation (03CH12-HY) |
| Filter | Wainwright | WHKX12-270 0-3000-18000 -60ST | SN2 | 3 GHz Highpass | Mar. 24, 2017 | Oct. 13, 2017 ~ Oct. 17, 2017 | Mar. 23, 2018 | Radiation (03CH12-HY) |
| Filter | Wainwright | WLKS1200-1 2SS | SN2 | 1.2G Low Pass | Mar. 24, 2017 | Oct. 13, 2017 ~ Oct. 17, 2017 | Mar. 23, 2018 | Radiation (03CH12-HY) |
| Antenna Mast | EMEC | AM-BS-4500- B | N/A | 1m~4m | N/A | Oct. 13, 2017 ~ Oct. 17, 2017 | N/A | Radiation (03CH12-HY) |
| Turn Table | EMEC | TT2000 | N/A | 0~360 Degree | N/A | Oct. 13, 2017 ~ Oct. 17, 2017 | N/A | Radiation (03CH12-HY) |
| Attenuator | Fairview Microwave | SA18S5W-10 | n/a | 10db | Mar. 24, 2017 | Oct. 13, 2017 ~ Oct. 17, 2017 | Mar. 23, 2018 | Radiation (03CH12-HY) |
| SHF-EHF Horn Antenna | SCHWARZBE CK | BBHA 9170 | BBHA9170 576 | 18GHz ~ 40GHz | Apr. 27, 2017 | Oct. 13, 2017 ~ Oct. 17, 2017 | Apr. 26, 2018 | Radiation (03CH12-HY) |
| Preamplifier | MITEQ | TTA1840-35- HG | 1887435 | 18GHz~40GHz | Jul. 18, 2017 | Oct. 13, 2017 ~ Oct. 17, 2017 | Jul. 17, 2018 | Radiation (03CH12-HY) |

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330M Page Number : 19 of 20
Report Issued Date : Nov. 08, 2017
Report Version : Rev. 02

Report No. : FR790120-02A

5 Uncertainty of Evaluation

Uncertainty of Radiated Emission Measurement (30 MHz ~ 1000 MHz)

| Measuring Uncertainty for a Level of Confidence | 5.10 |
|---|------|
| of 95% (U = 2Uc(y)) | 3.10 |

Uncertainty of Radiated Emission Measurement (1000 MHz ~ 18000 MHz)

| Measuring Uncertainty for a Level of Confidence | 5.20 |
|---|------|
| of 95% (U = 2Uc(y)) | 5.20 |

Uncertainty of Radiated Emission Measurement (18000 MHz ~ 40000 MHz)

| Measuring Uncertainty for a Level of Confidence | 4.70 |
|---|------|
| of 95% (U = 2Uc(y)) | 4.70 |

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7MC330M Page Number : 20 of 20
Report Issued Date : Nov. 08, 2017
Report Version : Rev. 02

Report No.: FR790120-02A

Appendix A. Radiated Spurious Emission

| Toot Engineer | | Temperature : | 23~25°C |
|-----------------|----------------------------------|---------------------|---------|
| Test Engineer : | Ray Chen, J.C. Liang and Nick Yu | Relative Humidity : | 59~63% |

2.4GHz 2400~2483.5MHz

BT (Band Edge @ 3m)

| вт | Note | Frequency | Level | Over | Limit | Read | Antenna | Cable | Preamp | Ant | Table | Peak | Pol. |
|------------------|------|-----------|------------|--------|------------|--------|----------|--------|--------|--------|-------|-------|-------|
| | | | | Limit | Line | Level | Factor | Loss | Factor | Pos | Pos | Avg. | |
| | | (MHz) | (dBµV/m) | (dB) | (dBµV/m) | (dBµV) | (dB/m) | (dB) | (dB) | (cm) | (deg) | (P/A) | (H/V) |
| | | 2383.64 | 42.67 | -31.33 | 74 | 42.82 | 27.31 | 4.03 | 31.49 | 380 | 46 | Р | Н |
| | | 2383.64 | 17.9 | -36.1 | 54 | - | - | - | - | - | - | Α | Н |
| | * | 2441 | 93.56 | - | - | 93.43 | 27.53 | 4.07 | 31.47 | 380 | 46 | Р | Н |
| | * | 2441 | 68.79 | - | - | - | - | - | - | - | - | Α | Н |
| | | 2486.98 | 42.8 | -31.2 | 74 | 42.52 | 27.64 | 4.11 | 31.47 | 380 | 46 | Р | Н |
| BT | | 2486.98 | 18.03 | -35.97 | 54 | - | - | - | - | - | - | Α | Н |
| CH 39 2441MHz | | 2373.56 | 42.63 | -31.37 | 74 | 42.8 | 27.31 | 4.01 | 31.49 | 246 | 328 | Р | V |
| 244 HVIITIZ | | 2373.56 | 17.86 | -36.14 | 54 | - | - | - | - | - | - | Α | V |
| | * | 2441 | 102.27 | - | - | 102.44 | 27.53 | 4.07 | 31.47 | 246 | 328 | Р | ٧ |
| | * | 2441 | 77.8 | - | - | - | - | - | - | - | - | Α | V |
| | | 2486.28 | 42.8 | -31.2 | 74 | 42.52 | 27.64 | 4.11 | 31.47 | 246 | 328 | Р | V |
| | | 2486.28 | 18.03 | -35.97 | 54 | - | - | - | - | - | - | Α | V |

Remark

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 Page Number

: A-1 of 4

^{1.} No other spurious found.

^{2.} All results are PASS against Peak and Average limit line.

2.4GHz 2400~2483.5MHz

BT (Harmonic @ 3m)

| вт | Note | Frequency | Level | Over | Limit | Read | Antenna | Cable | Preamp | Ant | Table | Peak | Pol. |
|-------------|------|---|------------|---------------|--------------------|-------------------|-----------------|--------------|-------------|---------------|-------|---------------|------|
| | | (MHz) | (dBµV/m) | Limit (dB) | Line (dBµV/m) | Level (dBµV) | Factor (dB/m) | Loss (dB) | Factor (dB) | Pos (cm) | | Avg. (P/A) | |
| BT CH 39 | | 4882 | 37.64 | -36.36 | 74 | 57.27 | 31.88 | 6.21 | 58.24 | 100 | 0 | Р | Н |
| | | 4882 | 12.87 | -41.13 | 54 | - | - | - | - | - | - | Α | Н |
| | | 7323 | 43.17 | -30.83 | 74 | 56.99 | 37.22 | 7.72 | 59.1 | 100 | 0 | Р | Н |
| | | 7323 | 18.4 | -35.6 | 54 | - | - | - | - | - | - | Α | Н |
| | | 4882 | 36.91 | -37.09 | 74 | 56.54 | 31.88 | 6.21 | 58.24 | 100 | 0 | Р | V |
| 2441MHz | | 4882 | 12.14 | -41.86 | 54 | - | - | - | - | - | - | Α | V |
| | | 7323 | 43.51 | -30.49 | 74 | 57.33 | 37.22 | 7.72 | 59.1 | 100 | 0 | Р | V |
| | | 7323 | 18.74 | -35.26 | 54 | - | - | - | - | - | - | Α | V |
| Remark | | No other spurious found. All results are PASS against Peak and Average limit line. | | | | | | | | | | | |

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978

Note symbol

Report No. : FR790120-02A

| * | Fundamental Frequency which can be ignored. However, the level of any unwanted emissions | | | | | | |
|-----|--|--|--|--|--|--|--|
| | shall not exceed the level of the fundamental frequency. | | | | | | |
| ! | Test result is over limit line. | | | | | | |
| P/A | Peak or Average | | | | | | |
| H/V | Horizontal or Vertical | | | | | | |

SPORTON INTERNATIONAL INC. Page Number : A-3 of 4

TEL: 886-3-327-3456 FAX: 886-3-328-4978

A calculation example for radiated spurious emission is shown as below:

Report No.: FR790120-02A

| WIFI | Note | Frequency | Level | Over | Limit | Read | Antenna | Cable | Preamp | Ant | Table | Peak | Pol. |
|---------|------|-----------|------------|--------|------------|---------------------|----------|--------|--------|--------|-------|-------|-------|
| Ant. | | | | Limit | Line | Level | Factor | Loss | Factor | Pos | Pos | Avg. | |
| 1+2 | | (MHz) | (dBµV/m) | (dB) | (dBµV/m) | (dB _µ V) | (dB/m) | (dB) | (dB) | (cm) | (deg) | (P/A) | (H/V) |
| 802.11b | | 2390 | 55.45 | -18.55 | 74 | 54.51 | 32.22 | 4.58 | 35.86 | 103 | 308 | Р | Н |
| CH 01 | | | | | | | | | | | | | |
| 2412MHz | | 2390 | 43.54 | -10.46 | 54 | 42.6 | 32.22 | 4.58 | 35.86 | 103 | 308 | Α | Н |

1. Level($dB\mu V/m$) =

Antenna Factor(dB/m) + Cable Loss(dB) + Read Level(dB μ V) - Preamp Factor(dB)

2. Over Limit(dB) = Level(dB μ V/m) – Limit Line(dB μ V/m)

For Peak Limit @ 2390MHz:

- 1. Level(dBµV/m)
- = Antenna Factor(dB/m) + Cable Loss(dB) + Read Level(dBµV) Preamp Factor(dB)
- $= 32.22(dB/m) + 4.58(dB) + 54.51(dB\mu V) 35.86 (dB)$
- $= 55.45 (dB\mu V/m)$
- 2. Over Limit(dB)
- = Level(dBµV/m) Limit Line(dBµV/m)
- $= 55.45(dB\mu V/m) 74(dB\mu V/m)$
- = -18.55(dB)

For Average Limit @ 2390MHz:

- Level(dBµV/m)
- = Antenna Factor(dB/m) + Cable Loss(dB) + Read Level(dBµV) Preamp Factor(dB)
- $= 32.22(dB/m) + 4.58(dB) + 42.6(dB\mu V) 35.86 (dB)$
- $= 43.54 (dB\mu V/m)$
- 2. Over Limit(dB)
- = Level($dB\mu V/m$) Limit Line($dB\mu V/m$)
- $= 43.54(dB\mu V/m) 54(dB\mu V/m)$
- = -10.46(dB)

Both peak and average measured complies with the limit line, so test result is "PASS".

SPORTON INTERNATIONAL INC. Page Number : A-4 of 4

TEL: 886-3-327-3456 FAX: 886-3-328-4978

Appendix B. Radiated Spurious Emission Plots

| Tool Fusiness . | | Temperature : | 23~25°C |
|-----------------|----------------------------------|---------------------|---------|
| Test Engineer : | Ray Chen, J.C. Liang and Nick Yu | Relative Humidity : | 59~63% |


Report No. : FR790120-02A

SPORTON INTERNATIONAL INC. Page Number


TEL: 886-3-327-3456 FAX: 886-3-328-4978

2.4GHz 2400~2483.5MHz


BT (Band Edge @ 3m)



TEL: 886-3-327-3456 FAX: 886-3-328-4978



TEL: 886-3-327-3456 FAX: 886-3-328-4978




TEL: 886-3-327-3456 FAX: 886-3-328-4978



Report No.: FR790120-02A


Appendix C. Duty Cycle Plots

DH5 on time (One Pulse) Plot on Channel 39



Date: 17.0CT.2017 08:17:14

on time (Count Pulses) Plot on Channel 39



Date: 17.0CT.2017 08:18:11

Note:

- 1. Worst case Duty cycle = on time/100 milliseconds = $2 \times 2.89 / 100 = 5.78 \%$
- 2. Worst case Duty cycle correction factor = 20*log(Duty cycle) = -24.77 dB
- 3. DH5 has the highest duty cycle worst case and is reported.

SPORTON INTERNATIONAL INC.

Page Number

: C-1 of 2



Duty Cycle Correction Factor Consideration for AFH mode:

Bluetooth normal hopping rate is 1600Hz and reduced to 800Hz in AFH mode; due to the reduced number of hopping frequencies, with the same packet configuration the dwell time in each channel frequency within 100msec period is longer in AFH mode than normal mode.

In AFH mode, the minimum hopping frequencies are 20, to get the longest dwell time DH5 packet is observed; the period to have DH5 packet completing one hopping sequence is

 $2.89 \text{ ms } \times 20 \text{ channels} = 57.8 \text{ ms}$

There cannot be 2 complete hopping sequences within 100ms period, considering the random hopping behavior, maximum 2 hops can be possibly observed within the period. [100ms / 57.6ms] = 2 hops

Thus, the maximum possible ON time:

2.89 ms x 2 = 5.78 ms

Worst case Duty Cycle Correction factor, which is derived from the maximum possible ON time,

 $20 \times log(5.78 \text{ ms}/100\text{ms}) = -24.77 \text{ dB}$

TEL: 886-3-327-3456 FAX: 886-3-328-4978