

Appendix D. SAR Test Setup Photos

Hotspot Exposure Condition



Front at 10 mm



Back at 10 mm



Right Side at 10 mm



Left Side at 10 mm

Body-worn Exposure Condition



Front with Holster at 0 mm



Right Side with Holster at 0 mm



Left Side with Holster at 0 mm

Extremity Exposure Condition



Back at 0 mm