

Appendix E. SAR Test Setup Photos

Hotspot Exposure Condition



Front at 10 mm



Top Side at 10 mm



Left Side at 10 mm



Right Side at 10 mm

Body-worn Exposure Condition



Front with Holster at 0 mm



Left Side at 0 mm



Right Side at 0 mm



Left Side with Holster at 0 mm



Right Side with Holster at 0 mm



Left Side with Holster with Headset at 0 mm



Right Side with Holster with Headset at 0 mm

Product Specific Exposure Condition



Back at 0 mm

PD Test Setup Photo



Front with holster at 2 mm



Back at 2 mm



Left Side with holster at 25 mm



Right Side with holster at 25 mm

Supplemental SAR Setup Photo



Front at 25 mm



Left Side at 25 mm



Right Side at 25 mm