

Appendix D. SAR Test Setup Photos


Hand Exposure Condition



Bottom Face at 0mm



Edge 1 at 0mm



Edge 2 at 0mm



Edge 3 at 0mm



Edge 4 at 0mm

Body Exposure Condition



Bottom Face at 0mm