



Appendix D. SAR Test Setup Photos

Body-worn Exposure Condition



Front + Battery 1 at 15 mm



Back + Battery 1/2/3 at 15 mm



Back + Holster + Battery 1 at 0 mm



Back + Battery 4 at 15 mm



Product Specific Exposure Condition



Front + Battery 1 at 0 mm



Back + Battery 1 at 0 mm




Right Side + Battery 1/2/3 at 0 mm



Right Side + Battery 4 at 0 mm



Left Side+ Battery 1 at 0 mm



Top Side at + Battery 1 at 0 mm