

Appendix G. SAR Test Setup Photos

Head Exposure Condition



Right Cheek at 0mm



Right Tilted at 0mm



Left Cheek at 0mm



Left Tilted at 0mm

Hotspot Exposure Condition




Front at 10 mm



Back at 10 mm



Left Side at 10 mm



Right Side at 10 mm



Top Side at 10 mm

Body-worn Exposure Condition



Front at 10 mm



Front at 15 mm



Back + Holster at 0 mm



Back at 15 mm


Product Specific Exposure Condition



Front at 0 mm



Back at 0 mm



Right Side at 0 mm



Left Side at 0 mm



Top Side at 0 mm

G-Sensor Exposure Condition



Left Side at 25 mm



Right Side at 25 mm



Back at 25 mm


PD Exposure Condition




Front at 2 mm




Back at 2 mm



Left Side at 2 mm



Right Side at 2 mm



Top Side at 2 mm