


## Appendix D. Test Setup Photos

## **EUT With Battery1 & With Scanner**



**Front View** 



Left Side View



**Right Side View** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55CH Page Number : D1 of D3
Report Issued Date : Feb. 10, 2014

Report No.: HA3O1108-01A

Report Version : Rev. 01



Report No.: HA3O1108-01A

## **EUT With Battery1 & Without Scanner**



**Front View** 



Left Side View



Right Side View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55CH Page Number D2 of D3
Report Issued Date : Feb. 10, 2014
Report Version : Rev. 01



Report No.: HA3O1108-01A

## **EUT With Battery2 & With Scanner**



**Front View** 



Left Side View



**Right Side View** 

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: UZ7TC55CH Page Number D3 of D3
Report Issued Date : Feb. 10, 2014
Report Version : Rev. 01