

Appendix F. SAR Test Setup Photos**Head Exposure Condition****Right Cheek at 0mm****Right Tilted at 0mm****Left Cheek at 0mm****Left Tilted at 0mm**

Hotspot Exposure Condition



Front at 10 mm



Back at 10 mm



Right Side at 10 mm



Left Side at 10 mm



Top Side at 10 mm



Bottom Side at 10 mm

Body-worn Exposure Condition



Front at 15 mm



Back at 15 mm



Front with Soft Holster at 0 mm



Back with Soft Holster at 0 mm

Product Specific Exposure Condition



Front at 0 mm



Back at 0 mm



Right Side at 0 mm




Left Side at 0 mm



Top Side at 0 mm

PD Exposure Condition




Front at 2 mm



Back at 2 mm



Right Side at 2 mm



Left Side at 2 mm



Top Side at 2 mm