

Correspondence by Project**Project Number:**

-1825710239

Correspondence Number	Memo
V4TJR2TX1-1	1) The user manual provides an incomplete FCC statement. Please provide a corrected user manual. Please see the attached corrected user manual. 2) The EUT appears to have a USB port, however it was not connected during testing. Please explain the purpose of this port. This port is for service/diagnostic purposes only and is not used during transmit operation.