


8. SETUP PHOTOS

RADIATED RF MEASUREMENT SETUP FOR PORTABLE CONFIGURATION


X-AXIS PHOTO




X-AXIS WITH AC ADAPTER PHOTO



Y-AXIS PHOTO




Y-AXIS WITH AC ADAPTER PHOTO



Z-AXIS PHOTO



Z-AXIS WITH AC ADAPTER PHOTO

**END OF REPORT**