




3731 Rutledge Road
Albuquerque, NM 87109
505-856-5285 phone
505-856-5942 fax

FCC ID Location on Module
July 18, 2008

FLOM TEST LABS
3356 N San Marcos Suite 107
Chandler AZ, 85225

Dear Jackie Pillai:

The picture shown is of the Monitron Module currently under test by FLOM Labs. The FCC ID is located as shown and during production will be part of the bottom layer copper as previously discussed.



PWA Bottom

Best Regards,

A handwritten signature in black ink, appearing to read "Max A. Lopez".

Max A. Lopez
Engineer Supervisor
Ext. 112

• • • • • • • • • • • • • • • •

www.Monitron.US