

Explanation for FCC's RT

TO: Federal Communication Commission

Please kindly be notified that we, ZINUS(Xiamen) Co., Ltd herein explain the cease transmission time mentioned in the original operational description to the FCC ID: VB61101-01 for the following reason:


1. Spelling error: the designed ceasing time for the transmission should be 1.0-1.5s but not 10-15s.

Based the reason above, we decided to reverse the operational description as "After the switch triggered, the transmission will maintain no more than 5s and then be turned off immediately".

Please kindly accept our explanation.

Thank you.

Sincerely,



March 17, 2011

(Signature)

Company: ZINUS(Xiamen) Co.,Ltd

Tel: 86-592-6662920

Fax:86-592-6296624

Email: yccho@zinus.com.cn