



HERMON LABORATORIES

September 25, 2007

American TCB  
6731 Whittier Ave  
Suite C110  
McLean, VA 22101  
Attn: Mr. T. Johnson, Examining Engineer

RE: your e-mail dated September 20, 2007; Arad Technologies Ltd.  
**FCC ID:VIDCENTRON, ATCB005437**

Dear Mr. Johnson,  
Please find below the answers to your questions:

- 1) The photo of the antenna second side was added, revised file "Antenna\_photo\_18095\_rev1" was uploaded on September 25, 2007 via Internal Photos folder;
- 2) The corrected test report ARARAD\_FCC.18095\_rev1 with re-measured OBW (Table 7.1.2, Plot 7.1.1) was uploaded on September 25, 2007.

Sincerely,

Marina Cherniavsky,  
certification engineer  
Hermon Laboratories