



American Telecommunications Certification Body Inc.
6731 Whittier Ave, McLean, VA 22101

September 21, 2007

RE: ATCB005442

FCC ID: VITMAX1036127M

I have a few comments on this application. Depending on your responses, kindly understand there may be additional comments.

1. Your external photos did not show the top and bottom of the device clearly.
Please update us with better photos and also provide additional photos that allow us to see the left and right side of this device.

~~~~~  
~ George Chen  
~ <mailto:george@atcb.com>  
~ Taiwan Mobile: +886 930600123  
~ SKYPE: georgeshirley  
~~~~~

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.