



MASIMO AMERICAS  
Forty Parker  
Irvine, CA 92618

01-09-2015

Federal Communications Commission  
Authorization and Evaluation Division  
7435 Oakland Mills Road  
Columbia , Maryland 21046

To Whom it May Concern:

We attest to the following:

- Per FCC KDB 443999 D01 v01 and RSS 210 Annex 9, this device will not transmit in the 5600 - 5650 MHz band
- Per FCC KDB 848637, the device is a client device with no radar detection capability. The client software and associated drivers will not initiate any transmission on DFS frequencies without initiation by a master. This includes restriction on transmissions for beacons and support for ad-hoc peer-to-peer modes.
- Per FCC KDB 594280 D01 v01r02, the device complies with the requirements for software configuration control. The device meets the definition of FCC 15.202 client device and does not have the ability to be configured by end users or professional installers to operate outside the authorized bands
- Per FCC 15.407(c), the device will automatically discontinue transmission in case of either absence of information to transmit or operational failure.

Michael Clark

Signature