

Autonet Mobile

Tune up Procedure

I would like to confirm this device does not have tune up information, because the tune up is fixed by the manufacturer. Therefore, the user cannot tune up the device.

Conducted Peak power range is below:

GSM850 band: maximum power range is $32\pm1\text{dBm}$

GPRS850 (4down 1up) band: maximum power range is $32\pm1\text{dBm}$

GPRS850 (3down 2up) band: maximum power range is $31\pm1\text{dBm}$

GPRS850 (2down 3up) band: maximum power range is $30\pm1\text{dBm}$

GPRS850 (1down 4up) band: maximum power range is $29\pm1\text{dBm}$

PCS1900 band: maximum power range is $29\pm1\text{dBm}$

GPRS1900 (4down 1up) band: maximum power range is $29\pm1\text{dBm}$

GPRS1900 (3down 2up) band: maximum power range is $28\pm1\text{dBm}$

GPRS1900 (2down 3up) band: maximum power range is $27\pm1\text{dBm}$

GPRS1900 (1down 4up) band: maximum power range is $26\pm1\text{dBm}$

Sincerely,



Client's signature

Client's name / title: $\text{Doug Moeller / CTO}$