



Request for Class II Permissive Change

February 24, 2021

Federal Communication Commission
Equipment Authorization Division
Application Processing Branch
7435 Oakland Mills Road
Columbia, Maryland 21046

FCC ID : VPYLBEE5ZZ1PJ
Applicant : Murata Manufacturing Co., Ltd.

To Whom It May Concern:

This is to request a Class II permissive change for FCC ID: VPYLBEE5ZZ1PJ, originally granted on January 1, 2019 and all its permissive changes.

We changed the following points from the original model.

- Addition of master function for DFS bands (W53/W56)
Original firmware version: 0.0.0.27
New firmware version: 0.0.0.140
Note: There is no changes on 2.4GHz band (DSS, DTS).
11ac20/40/80 mode is disabled by software of host device by professional installer.
- Addition of one antenna type (Dipole) for 5GHz only

Meanwhile we submit the following documents related to this change. There is no change before and after change except for these documents.

<input checked="" type="checkbox"/>	Test Report
<input checked="" type="checkbox"/>	RF Exposure
<input checked="" type="checkbox"/>	External Photo
<input type="checkbox"/>	Internal Photo
<input type="checkbox"/>	User Manual
<input type="checkbox"/>	Label Drawing/ Location
<input type="checkbox"/>	Block Diagram
<input checked="" type="checkbox"/>	Specification
<input type="checkbox"/>	Schematic Diagram
<input type="checkbox"/>	Parts List

This time, we performed the testing and confirmed that this product still meets the minimum requirements of the applicable rules of FCC. Please refer to the test report submitted with this application.

Thank you for your attention to this matter.

Sincerely,

KENJI HAYASHIKOSHI
MURATA MANUFACTURING CO., LTD.