



Ralink Technology Corporation
5F, No. 36, Taiyuan street, Jhu-Bei City,
Hsin-Chu County 302, Taiwan, R.O.C

Date (15/09/2010)

BABT TCB
Balfour House,
Churchfield Road,
Walton-on-Thames,
Surrey,
KT12 2TD

REF: Class II permissive change, pursuant to section 2.1043, for FCC ID: VQF-RT3090-1T1R

Dear Sir or Madam,

Pursuant to section 2.1043, *Ralink Technology Corporation hereby submit a request for class II permissive change to our 802.11 b/g/n 1T1R WLAN Mini Card, model no.: RT3090, FCC ID: VQFRT3090-1T1R*

Description of the change:

1) *The product VQF-RT3090-1T1R will be installed in the following model of Tablet PCs:*

PC-A1001

The antenna connected for the VQF-RT3090-1T1R is located in the display of the Tablet PC and it have gain of less than 1 dBi. More detail about the antenna position and the gain and type of antenna are provided in operation description.

2) *Two-ways authentication is implemented for user's installable modules.*

Compliance / Responsibility statements:

-Test report according to Part 15C of original grant remains valid and applicable and they are representative of the compliance of this module once it is installed in the indicated Tablet PC.

-New exhibition (SAR test report) to demonstrate with RF exposure requirement are submitted with this application.

-the product remains compliant with all the applicable rules and requirements once installed in the PC-A1001 according to the configurations covered by this application and host product manufacturer will be instructed to follow the approved configuration.

-Changes in the configuration indicated in this application and final compliance of the host device +modules composite system fall under the responsibility of the host product manufacturer.

Sincerely,

A handwritten signature in black ink that appears to read 'Daniel Kang'.
Project Manager: Daniel Kang
Ralink Technology Corporation

Telephone Number: +886-3-560-0868

Email: Daniel_kang@ralinktech.com.tw