



1132 West 1700 North, Logan, Utah 84321



January 11, 2016

Federal Communications Commission
Equipment Authorization Branch
7435 Oakland Mills Road
Columbia, MD 21046

Re: Part 2.933 Change in Identification to FCC ID: VSF25589

Dear Sir or Madam,

I hereby request a change in identification in accordance to CFR 47 Part 2.933 of the FCC rules. The original identification used on the equipment prior to this application for Change in Identification is QV5MERCURY6EN. The date of the original grant of the equipment authorization is April 28, 2015.

I hereby certify that the equipment bearing the modified identification, FCC ID: VSF25589, does not differ from the original equipment.

I further certify that the original test results continue to be representative of and applicable to the equipment bearing the changed identification.

Sincerely,

Kent Campbell
Product Assurance Engineer