



1274 Anvilwood Ave., Sunnyvale, CA 94089 USA
Tel.: 408.732.9162 Fax.: 408.732.9164 <http://www.baclcorp.com>

2009-03-17

Federal Communications Commission
Authorization and Evaluation Division
7435 Oakland Mills Road
Columbia, MD 21046

RE: Request to supersede test report for FCC ID: W4DVCID788F

To Whom It May Concern:

Regarding FCC ID: W4DVCID788F, we are requesting to supersede the original test report due to a clerical error. On page 3 of the original report that was uploaded on 02/26/2009, the frequency states 434 MHz, but we would like to correct this to state 433.92 MHz. We would like to upload the corrected test report per the clients request so that we may correct this clerical error.

Thank you very much.

Sincerely,

Jessica Jiang, Technical Writer
Document Control Department
Bay Area Compliance Laboratories Corp.
1274 Anvilwood Avenue
Sunnyvale, CA 94089, USA
Tel: (408)-732-9162 (**Ext.3040**)
Email: document.control@baclcorp.com