
FCC ID location



Alliance eROU_781719L1 Label (Internal)

MODEL eROU_781719L1_N RATING: 39-57V, 0.82-0.58A	SOLiD Alliance FCC ID: W6UER781719	
Made in Korea SOLID, Inc 10,9th Floor, SOLiD Space, 220, Pangyoyeok-ro, Bundang-gu, Seongnam-si, Gyeonggi-do, Republic of Koreá, 13493 CUL us E324601 I.T.E		
This device complies with part 15 of the FCC Rules. Operatio (1) This device may not cause harmful interference, and (2) the received, including interference that may cause undesired op	CAN ICES-3(A)/NMB-3(A) on is subject to the following two conditions: his device must accept any interference	
	\bigcirc	
Part 90 and Part 20 Signal Boosters THIS IS A 90.219 CLASS B DEVICE WARNING. This is NOT a CONSUMER device. It is designed for installation by FCC LICENSEES and QUALIFIED INSTALLERS. You MUST have an FCC LICENSE or express consent of an FCC Licensee to operate this device. You MUST register Part 90 and Part 20 Class B signal boosters (as defined in 47 CFR 90.219) online at www.fcc.gov/signal-boosters/registration. Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation.		
WARNING: This is NOT a CONSUMER device. It is designed for ins		

SOLiD Alliance MODEL eROU_781719L1_N RATING: 39-57V ___, 0.82-0.58A FCC ID: W6UER781719 Made in Vietnam 10,9th Floor, SOLiD Space, 220, Pangyoyeok-ro, Bundang-gu, Seongnam-si, Gyeonggi-do, Republic of Koreá, 13493 This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation. Part 90 and Part 20 Signal Boosters THIS IS A 90.219 CLASS B DEVICE WARNING. This is NOT a CONSUMER device. It is designed for installation by FCC LICENSEES and QUALIFIED INSTALLERS. You MUST have an FCC LICENSE or express consent of an FCC Licensee to operate this device. You MUST register Part 90 and Part 20 Class B signal boosters (as defined in 47 CFR 90.219) online at www.fcc.gov/signal-boosters/registration. Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation. WARNING: This is NOT a CONSUMER device. It is designed for installation by an installer approved by an ISED

licensee. You MUST have an ISED LICENCE or the express consent of an ISED licensee to operate this device.



Alliance eROU_781719L1 Label (External)

MODEL eROU_781719L1_X RATING: 39-57V, 0.82-0.58A	SOLiD Alliance FCC ID: W6UER781719
10,9th Floor, SOLiD Space, 220, Pangyoyeok-ro, Bundang-gu, Seongnam-s	Made in Korea SOLID, Inc i, Gyeonggi-do, Republic of Korea, 13493
This device complies with part 15 of the FCC Rules. Operation is sub (1) This device may not cause harmful interference, and (2) this device received, including interference that may cause undesired operation.	ce must accept any interference
	\bigcirc
Part 90 and Part 20 Signal Boosters TI WARNING. This is NOT a CONSUMER device. It is designed for installation by FCC You MUST have an FCC LICENSE or express consent of an FCC Licensee to opera Part 20 Class B signal boosters (as defined in 47 CFR 90.219) online at www.fcc.gov use may result in significant forfeiture penalties, including penalties in excess of \$100	te this device. You MUST register Part 90 and //signal-boosters/registration. Unauthorized
WARNING: This is NOT a CONSUMER device. It is designed for installation licensee. You MUST have an ISED LICENCE or the express consent of an I	

SOLiD Alliance MODEL: eROU_781719L1_X RATING: 39-57V ___, 0.82-0.58A FCC ID: W6UER781719 Made in Vietnam 10,9th Floor, SOLiD Space, 220, Pangyoyeok-ro, Bundang-gu, Seongnam-si, Gyeonggi-do, Republic of Koreá, 13493 This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation. Part 90 and Part 20 Signal Boosters THIS IS A 90.219 CLASS B DEVICE WARNING. This is NOT a CONSUMER device. It is designed for installation by FCC LICENSEES and QUALIFIED INSTALLERS. You MUST have an FCC LICENSE or express consent of an FCC Licensee to operate this device. You MUST register Part 90 and Part 20 Class B signal boosters (as defined in 47 CFR 90.219) online at www.fcc.gov/signal-boosters/registration. Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation. WARNING: This is NOT a CONSUMER device. It is designed for installation by an installer approved by an ISED licensee. You MUST have an ISED LICENCE or the express consent of an ISED licensee to operate this device.



Alliance eROU_781719L2 Label (Internal)

MODEL eROU_781719L2_N RATING: 39-57V, 0.82-0.58A	SOLiD Alliance FCC ID: W6UER781719	
Made in Korea SOLID, Inc 10,9th Floor, SOLiD Space, 220, Pangyoyeok-ro, Bundang-gu, Seongnam-si, Gyeonggi-do, Republic of Korea, 13493		
This device complies with part 15 of the FCC Rules. Operatio (1) This device may not cause harmful interference, and (2) the received, including interference that may cause undesired op	his device must accept any interference	
	\bigcirc	
Part 90 and Part 20 Signal Boosters THIS IS A 90.219 CLASS B DEVICE WARNING. This is NOT a CONSUMER device. It is designed for installation by FCC LICENSEES and QUALIFIED INSTALLERS. You MUST have an FCC LICENSE or express consent of an FCC Licensee to operate this device. You MUST register Part 90 and Part 20 Class B signal boosters (as defined in 47 CFR 90.219) online at www.fcc.gov/signal-boosters/registration. Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation.		
WARNING: This is NOT a CONSUMER device. It is designed for ins licensee. You MUST have an ISED LICENCE or the express consen		

MODEL eROU_781719L2_N	SOLiD Alliance
RATING: 39-57V, 0.82-0.58A	FCC ID : W6UER781719
	Made in Vietnam
10,9th Floor, SOLiD Space, 220, Pangyoyeok-ro, Bundang-gu, Seongnam-s	SOLID, Inc si, Gyeonggi-do, Republic of Korea, 13493
	CUL US E324601 LISTED
This device complies with part 15 of the FCC Rules. Operation is sul (1) This device may not cause harmful interference, and (2) this devi received, including interference that may cause undesired operation.	ce must accept any interference
	$\overline{}$
Part 90 and Part 20 Signal Boosters T WARNING. This is NOT a CONSUMER device. It is designed for installation by FCC You MUST have an FCC LICENSE or express consent of an FCC Licensee to opera Part 20 Class B signal boosters (as defined in 47 CFR 90.219) online at www.fcc.go use may result in significant forfeiture penalties, including penalties in excess of \$10	ate this device. You MUST register Part 90 and v/signal-boosters/registration. Unauthorized
WARNING: This is NOT a CONSUMER device. It is designed for installatio licensee. You MUST have an ISED LICENCE or the express consent of an	



Alliance eROU_781719L2 Label (External)

MODEL eROU_781719L2_X RATING: 39-57V	SOLiD Alliance FCC ID: W6UER781719	
10,9th Floor, SOLiD Space, 220, Pangyoyeok-ro, Bundang-gu, Seongnam-	Made in Korea SOLID, Inc si, Gyeonggi-do, Republic of Korea, 13493	
	CULUS E324601 I.T.E CAN ICES-3(A)/NMB-3(A)	
This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.		
Part 90 and Part 20 Signal Boosters THIS IS A 90.219 CLASS B DEVICE WARNING. This is NOT a CONSUMER device. It is designed for installation by FCC LICENSEES and QUALIFIED INSTALLERS. You MUST have an FCC LICENSE or express consent of an FCC Licensee to operate this device. You MUST register Part 90 and Part 20 Class B signal boosters (as defined in 47 CFR 90.219) online at www.fcc.gov/signal-boosters/registration. Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation.		
WARNING: This is NOT a CONSUMER device. It is designed for installation by an installer approved by an ISED licensee. You MUST have an ISED LICENCE or the express consent of an ISED licensee to operate this device.		

SOLiD Alliance MODEL eROU_781719L2_X RATING: 39-57V ___, 0.82-0.58A FCC ID: W6UER781719 Made in Vietnam 10,9th Floor, SOLiD Space, 220, Pangyoyeok-ro, Bundang-gu, Seongnam-si, Gyeonggi-do, Republic of Koreá, 13493 This device complies with part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation. Part 90 and Part 20 Signal Boosters THIS IS A 90.219 CLASS B DEVICE WARNING. This is NOT a CONSUMER device. It is designed for installation by FCC LICENSEES and QUALIFIED INSTALLERS. You MUST have an FCC LICENSE or express consent of an FCC Licensee to operate this device. You MUST register Part 90 and Part 20 Class B signal boosters (as defined in 47 CFR 90.219) online at www.fcc.gov/signal-boosters/registration. Unauthorized use may result in significant forfeiture penalties, including penalties in excess of \$100,000 for each continuing violation. WARNING: This is NOT a CONSUMER device. It is designed for installation by an installer approved by an ISED

licensee. You MUST have an ISED LICENCE or the express consent of an ISED licensee to operate this device.

