

Date: 28 August 2014

**attn: Reviewing Engineer
Federal Communications Commission
7435 Oakland Mills Road
Columbia, MD 21046**

To Whom It May Concern:


The NNR + Switch, FCC ID: W8F800960000 and label is so small that it cannot include the statement specified in FCC Part 15 Sub-part A, Section 15.19 (a) (3) "This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions:

- (1) This device may not cause harmful interference and**
- (2) This device must accept any interference received, including interference that may cause undesired operation."**

Due to this reason, we are using the provisions of Part 15 Sub-part A, Section 15.19 (a) (5) and this statement appears in a prominent location in the user manual.

Please contact me if there is any information you may need.

**Thank you,
Signature:**

A circular stamp from Orpak Systems Ltd. is positioned over the signature line. The stamp contains the text: "31 Lechi St. Bnei Brak 51114", "Orpak Systems Ltd.", and "Reg. No. 510970064". A handwritten signature, "Gidi Segal", is written across the stamp and extends to the left.

Printed Name: Gidi Segal

**Quality Assurance Director
Orpak Systems Ltd.**