




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_16_QAM_3600MHz_Outer_Full




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_16_QAM_3600MHz_Inner_Full




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_16_QAM_3600MHz_Inner_1RB_Left




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_16_QAM_3600MHz_Inner_1RB_Right




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_16_QAM_3624.99MHz_Edge_1RB_Left




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_16_QAM_3624.99MHz_Edge_1RB_Right




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_16_QAM_3624.99MHz_Outer_Full




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_16_QAM_3624.99MHz_Inner_Full




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_16_QAM_3624.99MHz_Inner_1RB_Left




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_16_QAM_3624.99MHz_Inner_1RB_Right




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_16_QAM_3649.98MHz_Edge_1RB_Left




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_16_QAM_3649.98MHz_Edge_1RB_Right




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_16_QAM_3649.98MHz_Outer_Full




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_16_QAM_3649.98MHz_Inner_Full




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_16_QAM_3649.98MHz_Inner_1RB_Left




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_16_QAM_3649.98MHz_Inner_1RB_Right




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_64_QAM_3600MHz_Edge_1RB_Left




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_64_QAM_3600MHz_Edge_1RB_Right




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_64_QAM_3600MHz_Outer_Full




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_64_QAM_3600MHz_Inner_Full




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_64_QAM_3600MHz_Inner_1RB_Left




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_64_QAM_3600MHz_Inner_1RB_Right




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM 64 QAM_3624.99MHz_Edge_1RB_Left




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM 64 QAM_3624.99MHz_Edge_1RB_Right




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_64_QAM_3624.99MHz_Outer_Full




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_64_QAM_3624.99MHz_Inner_Full




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_64_QAM_3624.99MHz_Inner_1RB_Left




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_64_QAM_3624.99MHz_Inner_1RB_Right




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_64_QAM_3649.98MHz_Edge_1RB_Left




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_64_QAM_3649.98MHz_Edge_1RB_Right




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM 64 QAM_3649.98MHz_Outer_Full




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM 64 QAM_3649.98MHz_Inner_Full




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_64_QAM_3649.98MHz_Inner_1RB_Left




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_64_QAM_3649.98MHz_Inner_1RB_Right




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_256_QAM_3600MHz_Edge_1RB_Left




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_256_QAM_3600MHz_Edge_1RB_Right




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_256_QAM_3600MHz_Outer_Full




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_256_QAM_3600MHz_Inner_Full




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_256_QAM_3600MHz_Inner_1RB_Left




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_256_QAM_3600MHz_Inner_1RB_Right




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_256_QAM_3624.99MHz_Edge_1RB_Left




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_256_QAM_3624.99MHz_Edge_1RB_Right




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_256_QAM_3624.99MHz_Outer_Full




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_256_QAM_3624.99MHz_Inner_Full




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM 256 QAM 3624.99MHz Inner_1RB_Left




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM 256 QAM 3624.99MHz Inner_1RB_Right




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_256_QAM_3649.98MHz_Edge_1RB_Left




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_256_QAM_3649.98MHz_Edge_1RB_Right




n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_256_QAM_3649.98MHz_Outer_Full



n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_256_QAM_3649.98MHz_Inner_Full



n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_256_QAM_3649.98MHz_Inner_1RB_Left



n78d_30kHz_SISO_NTNV_100MHz_CP-OFDM_256_QAM_3649.98MHz_Inner_1RB_Right

