

802 N. Twin Oaks Valley Rd., Suite 105

San Marcos, CA 92069

Phone: (760) 471-2100

FAX: (760) 471-2121

[www.rfexposurelab.com](http://www.rfexposurelab.com)

Date: December 16, 2024

Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046 USA


**Re: Request Change in Identification**

Dear Examiner,

This change of identification request applies for FCC ID: **XO2SPB209A** as established in 47CFR 2.933(b) for a currently approved device. This application by DMS-Service LLC will establish a new FCC ID: **WUW-SPB209A** for purpose of marketing. The original grant to H&D Wireless AB will remain in effect per 2.933(b).

1. The original identification is FCC ID: XO2SPB209A
2. The original grant date is 10/12/2016
3. The equipment is electrically identical, only application and FCC ID are different
4. The original test results are applicable and representative of this changed device
5. Exterior photographs are included in this application

Sincerely,



Name: Jay Moulton  
Title: Vice President  
On behalf of Viavi Solutions Inc.  
Phone: (760) 471-2100